



ADDENDUM

Public Building Commission of Chicago | Richard J. Daley Center | 50 West Washington Street, Room 200 | Chicago, Illinois 60602 | (312) 744-3090 | pbochicago.com

ADDENDUM NO.: 01
PROJECT NAME: Property Management Services at the Richard J. Daley Center
CONTRACT NO.: PS3086
DATE OF ISSUE: September 7, 2023

NOTICE OF CHANGES, MODIFICATIONS, OR CLARIFICATIONS TO CONTRACT DOCUMENTS

The following changes, modifications, or clarifications are hereby incorporated and made an integral part of the Contract Documents. Unless clearly expressed otherwise by this Addendum, all terms and conditions defined in the original Contract Documents shall continue in full force and effect and shall have the same meaning in this Addendum. Issued Addenda represent responses/clarifications to various inquiries. Respondents shall be responsible for including all associated costs in their proposal.

ITEM NO. 1: CHANGE TO KEY DATES
None.

ITEM NO. 2: CHANGE TO REQUEST FOR PROPOSAL (RFP)
None.

ITEM NO. 3: REQUESTS FOR INFORMATION

RFI-1.

Question: Is the carpenter in house or outsourced?

Response: The carpenter position is outsourced.

RFI-2.

Question: How often are the elevator recall generators tested?

Response: The elevator recall generators are tested yearly.

RFI-3.

Question: What are the current hours of the Law Library?

Response: Monday through Friday 8:30am to 4:00pm. The law library is currently closed on the weekends.

RFI-4.

Question: Do the restrooms have uniform appliances?

Response: The building has over 450 restrooms. While many appliances are the same, several vary.

RFI-5.

Question: To change the lights in the courtrooms, does the Judge's bench move?

Response: The judge's bench is stationary. Lights above the judge's bench are changed with scaffolding and currently requires two engineers.

RFI-6.

Question: Is the paint in the courtrooms, flat, matte, other?

Response: The courtroom paint is custom. It is Benjamin Moore Eco (blended paint) with an eggshell finish.

RFI-7.

Question: Is the space in the pedway the only space available to let?

Response: Yes. The tenant amenity space in the pedway is the only space available for rent.

RFI-8.

Question: What is the square footage of the tenant space in the pedway?

Response: The approximate square footage for the pedway tenant amenity rental space is 705 square feet.

RFI-9.

Question: Are the leases within the building long-term leases?

Response: Cook County's and Mobilite's leases are long-term. The Illinois Workers Compensation Commission and Illinois Liquor Control Commission have leases through Intergovernmental Agreements. The Bail Bondsmen and ATM leases are not long term.

RFI-10.

Question: How is the MBE/WBE participation computed?

Response: Minority and Women Business Enterprise participation is calculated based on the dollars spent for operating services.

RFI-11.

Question: How many service calls are handled on a regular basis?

Response: Year to date, there have been approximately 11,780 service calls. Last month (July 2023) there were approximately 1,675.

RFI-12.

Question: Is there a custodial inventory?

Response: Please refer to 2015 Asbestos-Containing Building Material Re-Inspection Report.

RFI-13.

Question: Is the Building signatory to BOMA?

Response: The cleaning and security are signatory to BOMA. The engineers are not signatory to BOMA beginning January 1, 2024.

RFI-14.

Question: What is the snow removal boundary?

Response: The entire perimeter of the building, from sidewalk to building. The snow must also be removed from the entrance/exit ramps.

This Addendum includes the following attached Document(s):

1. 2015 Asbestos-Containing Building Material Re-Inspection Report, dated December 2015

END OF ADDENDUM NO. 01

2015 Asbestos-Containing Building Material Re-Inspection Report

**Site: Richard J. Daley Center
50 W. Washington Blvd.
Chicago, Illinois 60602**

Survey Date: December 2015

Carnow Conibear Project No.: A133670096




**Prepared For: *MB Real Estate*
50 W. Washington Blvd., Suite 1200
*Chicago, Illinois 60602***

2015 Asbestos-Containing Building Material Re-Inspection Report

**Site: Richard J. Daley Center
50 W. Washington Blvd.
Chicago, Illinois 60602**

Inspected by:




James Lehnhardt
Asbestos Building Inspector
(IDPH #100-4208)

Inspected by:



Douglas McCormick
Asbestos Building Inspector
(IDPH #100-08904)

Report by:



James Lehnhardt
Asbestos Building Inspector

Reviewed by:



Daniel Juneau
Director of Operations

TABLE OF CONTENTS

1.0	EXECUTIVE SUMMARY	1
2.0	INTRODUCTION	5
3.0	SCOPE OF SERVICES	6
4.0	SURVEY METHODOLOGY	7
5.0	TABLE INTERPRETATION	8
6.0	CONCLUSIONS AND RECOMMENDATIONS	9

ATTACHMENTS

Summary Tables - Inclusive List of ACM Materials - ALL FLOORS

Lower Level - Summary Table of Materials and Drawing

Concourse Level - Summary Table of Materials and Drawing

Lobby - Summary Table of Materials and Drawing

2nd Floor - Summary Table of Materials and Drawing

3rd Floor - Summary Table of Materials and Drawing

4th Floor - Summary Table of Materials and Drawing

5th Floor - Summary Table of Materials and Drawing

6th Floor - Summary Table of Materials and Drawing

7th Floor - Summary Table of Materials and Drawing

8th Floor - Summary Table of Materials and Drawing

9th Floor and 9th Floor Mechanical - Summary Table of Materials and Drawing

10th Floor - Summary Table of Materials and Drawing

11th Floor - Summary Table of Materials and Drawing

12th Floor - Summary Table of Materials and Drawing

13th Floor - Summary Table of Materials and Drawing

14th Floor - Summary Table of Materials and Drawing

15th Floor - Summary Table of Materials and Drawing

16th Floor - Summary Table of Materials and Drawing

17th Floor - Summary Table of Materials and Drawing

18th Floor - Summary Table of Materials and Drawing

19th Floor - Summary Table of Materials and Drawing

20th Floor - Summary Table of Materials and Drawing

21st Floor - Summary Table of Materials and Drawing

22nd Floor - Summary Table of Materials and Drawing

23rd Floor - Summary Table of Materials and Drawing

24th Floor - Summary Table of Materials and Drawing

25th Floor - Summary Table of Materials and Drawing

26th Floor - Summary Table of Materials and Drawing

27th Floor - Summary Table of Materials and Drawing

28th Floor - Summary Table of Materials and Drawing

29th Floor - Summary Table of Materials and Drawing

30th Floor - Summary Table of Materials and Drawing

31st Floor - Summary Table of Materials and Drawing

M-1 Floor - Summary Table of Materials and Drawing

M-2 Floor - Summary Table of Materials and Drawing

M-3 Floor - Summary Table of Materials and Drawing

Inspector Licenses and Certificates

1.0 EXECUTIVE SUMMARY

Carnow, Conibear & Assoc., Ltd. (Carnow Conibear) was retained by MB Real Estate Services, LLC to perform an asbestos-containing building material re-inspection at the Richard J. Daley Center located at 50 W. Washington Blvd., Chicago, Illinois 60602. The survey incorporated all accessible interior areas of the building.

The re-inspection consisted of visually inspecting the interior of the subject site to assess the condition and location of previously identified asbestos-containing building materials, and to consolidate previously prepared drawings to show all Asbestos Containing Materials on each individual floor. Carnow Conibear also assigned recommended response actions for damaged asbestos containing materials identified during the re-inspection process.

The survey identified the following damaged accessible asbestos-containing building materials in need of repair/removal:

2nd Floor

- Damaged Grey Cementitious Boards/Electrical Floor Boards located in 250-B and Electrical Closets. These materials should be repaired to a condition that completely contains asbestos fibers and labeled as an asbestos containing material or removed and replaced with new Non-Asbestos Containing Material.

3rd Floor

- Damaged Grey Cementitious Boards/Electrical Floor Boards located in 350-B and Electrical/Telephone Closets. These materials should be repaired to a condition that completely contains asbestos fibers and labeled as an asbestos containing material or removed and replaced with new Non-Asbestos Containing Material.

4th Floor

- Damaged Grey Cementitious Boards/Electrical Floor Boards located in Conveyor Room and Electrical Closets. These materials should be repaired to a condition that completely contains asbestos fibers and labeled as an asbestos containing material or removed and replaced with new Non-Asbestos Containing Material.

5th Floor

- Damaged Grey Cementitious Boards/Electrical Floor Boards located in 550-B and Electrical Closets. These materials should be repaired to a condition that completely contains asbestos fibers and labeled as an asbestos containing material or removed and replaced with new Non-Asbestos Containing Material.

6th Floor

- Damaged Grey Cementitious Boards/Electrical Floor Boards located in 650-B and Electrical/Telephone Closets. These materials should be repaired to a condition that completely contains asbestos fibers and labeled as an asbestos containing material or removed and replaced with new Non-Asbestos Containing Material.

7th Floor

- Damaged Grey Cementitious Boards/Electrical Floor Boards located in 750-B and Electrical/Telephone Closets. These materials should be repaired to a condition that completely contains asbestos fibers and labeled as an asbestos containing material or removed and replaced with new Non-Asbestos Containing Material.

8th Floor

- Damaged Grey Cementitious Boards/Electrical Floor Boards located in 850-B and Electrical Closets. These materials should be repaired to a condition that completely

contains asbestos fibers and labeled as an asbestos containing material or removed and replaced with new Non-Asbestos Containing Material.

9th Floor & 9M

- Damaged Grey Cementitious Boards/Electrical Floor Boards located in Electrical Closets and near elevator bays. These materials should be repaired to a condition that completely contains asbestos fibers and labeled as an asbestos containing material or removed and replaced with new Non-Asbestos Containing Material.

10th Floor

- Damaged Grey Cementitious Boards/Electrical Floor Boards located in 1050-B and Electrical Closets. These materials should be repaired to a condition that completely contains asbestos fibers and labeled as an asbestos containing material or removed and replaced with new Non-Asbestos Containing Material.

11th Floor

- Damaged Grey Cementitious Boards/Electrical Floor Boards located in Electrical Closets. These materials should be repaired to a condition that completely contains asbestos fibers and labeled as an asbestos containing material or removed and replaced with new Non-Asbestos Containing Material.

12th Floor

- Damaged Grey Cementitious Boards/Electrical Floor Boards located in 1250-B and Electrical Closets. These materials should be repaired to a condition that completely contains asbestos fibers and labeled as an asbestos containing material or removed and replaced with new Non-Asbestos Containing Material.

13th Floor

- Damaged Grey Cementitious Boards/Electrical Floor Boards located in 1300-B and Electrical Closets. These materials should be repaired to a condition that completely contains asbestos fibers and labeled as an asbestos containing material or removed and replaced with new Non-Asbestos Containing Material.

14th Floor

- Damaged Grey Cementitious Boards/Electrical Floor Boards located in 1400-A and Electrical Closets. These materials should be repaired to a condition that completely contains asbestos fibers and labeled as an asbestos containing material or removed and replaced with new Non-Asbestos Containing Material.

15th Floor

- Damaged Grey Cementitious Boards/Electrical Floor Boards located in 1500-A and Electrical Closets. These materials should be repaired to a condition that completely contains asbestos fibers and labeled as an asbestos containing material or removed and replaced with new Non-Asbestos Containing Material.

16th Floor

- Damaged Grey Cementitious Boards/Electrical Floor Boards located in 1600-A and Electrical Closets. These materials should be repaired to a condition that completely contains asbestos fibers and labeled as an asbestos containing material or removed and replaced with new Non-Asbestos Containing Material.

17th Floor

- Damaged Grey Cementitious Boards/Electrical Floor Boards located in 1700-A and Electrical Closets. These materials should be repaired to a condition that completely contains asbestos fibers and labeled as an asbestos containing material or removed and replaced with new Non-Asbestos Containing Material.

18th Floor

- Damaged Grey Cementitious Boards/Electrical Floor Boards located in 1800-A and Electrical Closets. These materials should be repaired to a condition that completely

contains asbestos fibers and labeled as an asbestos containing material or removed and replaced with new Non-Asbestos Containing Material.

19th Floor

- Damaged Grey Cementitious Boards/Electrical Floor Boards located in 1900-A and Electrical Closets. These materials should be repaired to a condition that completely contains asbestos fibers and labeled as an asbestos containing material or removed and replaced with new Non-Asbestos Containing Material.

20th Floor

- Damaged Grey Cementitious Boards/Electrical Floor Boards located in 2000-B and Electrical Closets. These materials should be repaired to a condition that completely contains asbestos fibers and labeled as an asbestos containing material or removed and replaced with new Non-Asbestos Containing Material.

21st Floor

- Damaged Grey Cementitious Boards/Electrical Floor Boards located in 2100-B and Electrical Closets. These materials should be repaired to a condition that completely contains asbestos fibers and labeled as an asbestos containing material or removed and replaced with new Non-Asbestos Containing Material.

22nd Floor

- Damaged Grey Cementitious Boards/Electrical Floor Boards located in 2200-B and Electrical Closets. These materials should be repaired to a condition that completely contains asbestos fibers and labeled as an asbestos containing material or removed and replaced with new Non-Asbestos Containing Material.

23rd Floor

- Damaged Grey Cementitious Boards/Electrical Floor Boards located in 2300-B and Electrical Closets. These materials should be repaired to a condition that completely contains asbestos fibers and labeled as an asbestos containing material or removed and replaced with new Non-Asbestos Containing Material.

24th Floor

- Damaged Grey Cementitious Boards/Electrical Floor Boards located in 2400-B and Electrical Closets. These materials should be repaired to a condition that completely contains asbestos fibers and labeled as an asbestos containing material or removed and replaced with new Non-Asbestos Containing Material.

25th Floor

- Damaged Grey Cementitious Boards/Electrical Floor Boards located in 2500-B and Electrical Closets. These materials should be repaired to a condition that completely contains asbestos fibers and labeled as an asbestos containing material or removed and replaced with new Non-Asbestos Containing Material.

26th Floor

- Damaged Grey Cementitious Boards/Electrical Floor Boards located in 2600-B and Electrical Closets. These materials should be repaired to a condition that completely contains asbestos fibers and labeled as an asbestos containing material or removed and replaced with new Non-Asbestos Containing Material.

27th Floor

- Damaged Grey Cementitious Boards/Electrical Floor Boards located in 2700-B and Electrical Closets. These materials should be repaired to a condition that completely contains asbestos fibers and labeled as an asbestos containing material or removed and replaced with new Non-Asbestos Containing Material.

28th Floor

- Damaged Electrical Floor Boards located in Electrical Closets. These materials should be repaired to a condition that completely contains asbestos fibers and labeled as an

asbestos containing material or removed and replaced with new Non-Asbestos Containing Material.

29th Floor

- Damaged Electrical Floor Boards located in Electrical Closets. These materials should be repaired to a condition that completely contains asbestos fibers and labeled as an asbestos containing material or removed and replaced with new Non-Asbestos Containing Material.

30th Floor

- Damaged Electrical Floor Boards located in Electrical Closets. These materials should be repaired to a condition that completely contains asbestos fibers and labeled as an asbestos containing material or removed and replaced with new Non-Asbestos Containing Material.

Carnow Conibear also noted during the survey that asbestos containing structural fireproofing is present above hard plaster ceilings on most floors of the building. Fireproofing was noted to have localized areas of physical damage. Access above hard plaster ceilings should be limited to personnel having appropriate training for asbestos as detailed in 29 CFR 1026.1101 (OSHA Construction Industry Standard). Additionally access into ceiling spaces should comply with Daley Center's existing Asbestos Operation & Maintenance Plan.

Carnow Conibear recommends incorporating this information into future demolition/renovation documents regarding the presence and location of asbestos-containing materials. This information should also be made available to all maintenance personal, outside contractors and applicable building occupants. All asbestos abatement activities shall be conducted by a licensed contractor in accordance with the Illinois Department of Public Health (IDPH), USEPA National Emissions Standards for Hazardous Air Pollutants (NESHAPS), Occupational Safety and Health Administration (OSHA) and City of Chicago regulations and requirements.

2.0 INTRODUCTION

Carnow, Conibear & Assoc., Ltd. (Carnow Conibear) was retained MB Real Estate to perform an asbestos-containing building material re-inspection at the Richard J. Daley Center located at 50 W. Washington Blvd., Chicago, Illinois. The asbestos re-inspection survey was conducted by Carnow Conibear representatives Mr. James Lehnhardt and Mr. Douglas McCormick. Both Mr. Lehnhardt and Mr. McCormick are licensed by the Illinois Department of Public Health (IDPH) as Asbestos Building Inspectors. See Attachment for copies of current inspector licenses and accreditations.

The asbestos re-inspection was conducted in several phases. The first phase consisted of reviewing previous asbestos inspection and abatement data, followed by a walk-through survey of the subject building to assess the conditions and locations of previously identified asbestos-containing building materials and if necessary, to locate any additional suspect asbestos-containing building material previously not identified.

The final phase included generating an asbestos re-inspection summary report containing the description and location of all accessible asbestos-containing building materials. Tables and drawings are provided that list each type of accessible building material identified by homogeneous area and the location of the materials. Damaged materials were identified and approximate location(s) indicated on the corresponding drawing.

3.0 SCOPE OF SERVICES

The purpose of the asbestos re-inspection was to assess the condition and location of previously identified asbestos-containing building material and locate any suspect asbestos-containing materials previously not identified within the interior of the building. To achieve this purpose, the following procedures are performed:

- Historical Data Review - to verify accuracy of previous inspection data and documentation.
- Visual Inspection – to determine the location of suspect materials.
- Material Assessment – to determine to condition of the material along with an evaluation of any potential for future damage.
- Reporting – to prepare a summary report documenting the inspection findings and providing recommendations as warranted.

Because a destructive survey was not performed, the possibility exists that some suspect asbestos-containing building material is located in inaccessible areas such as pipe chases, under carpet, above plaster ceilings, or between walls. Carnow Conibear did make every reasonable effort to locate hidden mechanical systems or other inconspicuous materials during the re-inspection process.

4.0 SURVEY METHODOLOGY

Carnow Conibear completed the asbestos re-inspection by following inspection procedures identified in AHERA for asbestos building surveys. AHERA addresses specific inspection procedures for school buildings. AHERA's inspection procedures although defined for schools, are considered "state of the art" industry standard.

Following AHERA procedures, the asbestos inspector categorized all suspect asbestos containing materials into one of the following categories:

- **Surfacing Materials:** Sprayed or troweled on materials, such as fire proofing and plaster applied for acoustical, decorative, or fire safety purposes.
- **Thermal System Insulation:** Insulation applied to pipes, pipe joints, tanks, breeching, or other mechanical system components to prevent heat loss or gain, or to control water condensation.
- **Miscellaneous Materials:** All other building material, other than glass, wood, rubber, or plastic, typically used as architectural finishes, such as floor tile or ceiling tile. Does not include thermal system insulation or surfacing material.

In addition to the three (3) categories of ACM, materials are also grouped into homogeneous areas. A homogeneous area (HA) is a material determined by the inspector to be similar in color, texture, composition, and installation date. The body of this report, including exhibit drawings, differentiates all materials by HA designation.

The results of the inspection confirmed the presence of ACM at the subject site. See Attachments and tables summarizing asbestos containing and non-asbestos containing materials identified during the survey.

5.0 TABLE INTERPRETATION

Each floor at Richard J. Daley Center contains a table and a drawing. Each table is titled "Summary of Asbestos Containing Bulk Sampling" and includes the results of each suspect asbestos containing material identified on that particular floor. Each Drawing is titled "Locations of Asbestos Containing Materials". While the Table lists all materials identified on each floor of the building the drawing identifies the location of each confirmed or assumed asbestos containing material only.

6.0 CONCLUSIONS AND RECOMMENDATIONS

Carnow, Conibear & Assoc., Ltd. (Carnow Conibear) was retained by MB Real Estate to perform an asbestos-containing building material re-inspection survey at the Richard J. Daley Center located at 50 W. Washington Blvd., Chicago, Illinois. The survey incorporated all accessible interior areas of the building. Based on the survey results, Carnow Conibear recommends the following:

- Incorporate the data from this report into future demolition/renovation documents regarding the presence of asbestos-containing materials.
- Conduct periodic surveillance of each confirmed or assumed asbestos-containing building material every six to twelve months. Any changes in the condition of the asbestos containing building materials should be noted and an appropriate response action implemented.
- Repair or remove damaged grey cementitious boards/panels as detailed in report. If repair of panels is selected each panel should be labeled as an asbestos containing material. Include training and communication regarding the location of this material to applicable building personnel and instruct caution not to further damage material during routine maintenance activities.
- All future asbestos removal and/or demolition/renovation work involving the asbestos-containing building materials shall be conducted by a licensed contractor in accordance with IDPH, NESHAPS, OSHA and City of Chicago regulations and requirements.
- Prior to demolition, remove, dispose, and/or recycle all regulated materials as identified in this report.

Carnow Conibear has applied prevailing industry standards and reasonable judgment and effort within the scope of work outlined in Carnow Conibear's proposal, while conducting the asbestos-containing material survey. The standards, judgment, and effort used by Carnow Conibear personnel to investigate, assess, and determine the presence of potential environmental hazards and liabilities associated with the subject building are consistent with requirements outlined in federal and state guidelines. Carnow Conibear makes no warranty, express or implied, that the findings and interpretations in this report are a complete representation hazards and liabilities, associated with the building. Findings presented in this report are only indicative of conditions present during the time of the investigation and cannot be used to predict potential future or previous health effects on building occupants. The services performed by Carnow Conibear on this project have been conducted in a professional manner consistent with industry standards at the time of the survey and re-inspection. There may be materials that were not identified, because they were located in inaccessible areas and not available at the time of inspection. Carnow Conibear made every reasonable effort to locate mechanical systems and other inconspicuous materials.

The information contained in this report was prepared based upon the specific parameters requested by MB Real Estate Services, LLC and regulations in force at the time of the report. The information herein is only for the specific use of MB Real Estate Services, LLC and Carnow Conibear. Carnow Conibear accepts no responsibility for the use, reuse, interpretation, or reliance by other parties on the information contained herein, unless written authorization has

been obtained from Carnow Conibear. Carnow Conibear bears no responsibility for the implementation of recommendations included in this report unless specifically requested to do so by MB Real Estate Services, LLC.


Summary of Asbestos Bulk Sampling - Lower Level

Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
1	Terazzo	MISC	No	Lower Level-Hallway and Elevator Lobby.	X			Good Condition	
3	12" x 12" Black with White Specks Floor Tile	MISC	No	Lower Level-Variou Areas.			X	N/A	
4	Mastic on 12" x 12" Black with White Specks Floor Tile	MISC	No	Lower Level-Variou Areas.			X	N/A	
13	Carpet Mastic	MISC	No	Lower Level-Throughout Floor.			X	N/A	
17	Adhesive on 4" Black Vinyl Baseboard	MISC	No	Lower Level-Throughout Floor.			X	N/A	
19	1' x 1' Ceiling Tile	MISC	Yes	Lower Level-LL00 J Office.			X	N/A	
20	Adhesive on 1' x 1' Ceiling Tile	MISC	Yes	Lower Level-LL00 J Office.	X			Good Condition	
21	2' x 2' Textured Ceiling Tile	MISC	Yes	Lower Level-Variou Offices and Elevator Lobby.			X	N/A	
24	Plaster	SURF	Yes	Lower Level-Throughout Floor.			X	N/A	
27	Drywall/Joint Compound	MISC	No	Lower Level-throughout Floor.			X	N/A	
28	Textured Paint			Lower Level-Court Rooms LL-02 and LL-04.			X	N/A	
61	Grey Sealant on HVAC	MISC	No	Lower Level-Throughout Floor above Drop Ceilings.			X	N/A	
63	Red Duct Caulk	MISC	No	Lower Level-Throughout Floor above Drop Ceilings.		X		Good Condition	
64	Brown Duct Sealant	MISC	No	Lower Level-Throughout Floor above Drop Ceilings.			X	N/A	
80	Large 30" Pipe	TSI	YES	Lower Level-LL-00 K.			X	N/A	
81	Small Domestic Pipe	TSI	Yes	Lower Level-Visible Throughout Boiler Room and Mech. Spaces. May also be located in inaccessible areas.		X		Good Condition	
82	Drain Fitting	TSI	Yes	Lower Level-LL-00 K.			X	N/A	
83	Canvas Tape on HVAC	MISC	No	Lower Level-Visible Throughout Boiler Room and Mech. Spaces. May also be located in inaccessible areas.		X		Good Condition	
84	Black Adhesive Associated with Canvas Tape	MISC	No	Lower Level-Visible Throughout Boiler Room and Mech. Spaces. May also be located in inaccessible areas.			X	N/A	
85	Low-Pressure Steam Pipe	TSI	Yes	Lower Level-Boiler Room and Mechanical Space.		X		Good Condition	
86	Hi-Pressure Steam Pipe	TSI	Yes	Lower Level-Boiler Room and Mechanical Space.		X		Good Condition	

Summary of Asbestos Bulk Sampling - Lower Level

Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
87	Fitting on Water Make-up	TSI	Yes	Lower Level-Boiler Room and Mechanical Space.		X		Good Condition	
88	West Water Tank	TSI	Yes	Lower Level-Mechanical Space.			X	N/A	
89	East Water Tank	TSI	Yes	Lower Level-Mechanical Space.		X		Good Condition	
90	Grey Theramal System Insulation	TSI	Yes	Lower Level-Visible Throughout Boiler Room. May also be located in inaccessible areas.		X		Good Condition	
91	HVAC Corner	TSI	Yes	Lower Level-Visible Throughout Boiler Room. May also be located in inaccessible areas.		X		Good Condition	
92	Grey Condensate Return	TSI	Yes	Lower Level-Visible Throughout Boiler Room. May also be located in inaccessible areas.		X		Good Condition	
93	Fitting on Water Supply (Yellow)	TSI	Yes	Lower Level-Visible Throughout Boiler Room and Mech. Spaces. May also be located in inaccessible areas.		X		Good Condition	
94	Fitting on Chiller Thermal System Insulation	TSI	Yes	Lower Level-Visible Throughout Boiler Room and Mech. Spaces. May also be located in inaccessible areas.		X		Good Condition	
95	Fittings on Cold Water Pumps	TSI	Yes	Lower Level-Mechanical Space.		X		Good Condition	
96	Fitting on Drain Pipes	TSI	Yes	Lower Level-Throughout Floor may be consealed above drop ceilings.		X		Good Condition	
97	Fittings on Hot Water Pumps	TSI	Yes	Lower Level-Mechanical Space.		X		Good Condition	
98	Condenser Body	TSI	Yes	Lower Level-Boiler Room.		X		Good Condition	
99	Cooler Body	TSI	Yes	Lower Level-Boiler Room.		X		Good Condition	
100	Fittings on Cold Water to Coolers	TSI	Yes	Lower Level-Boiler Room.		X		Good Condition	
101	Boiler Flue	TSI	Yes	Lower Level-Boiler Room.		X		Good Condition	
102	Fittings on Boiler Water Feeder Pipes	TSI	Yes	Lower Level-Boiler Room.		X		Good Condition	
103	Valve Header (Orange)	TSI	Yes	Lower Level-Upper Level Boiler Room.		X		Good Condition	
104	Small Grey Tank	TSI	Yes	Lower Level-Boiler Room.		X		Good Condition	
105	Fittings associated with Small Grey Tank	TSI	Yes	Lower Level-Boiler Room.		X		Good Condition	
140	Leveling Compound	MISC	No	Lower Level-Throughout Floor under Carpet.			X	N/A	

Bold Indicates Asbestos and Assumed Asbestos Containing Materials.



Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
1	Terrazzo	X		Good Condition
20	Adhesive on 1' x 1' Ceiling Tile	X		Good Condition
63	Red Duct Caulk		X	Good Condition
81	Small Domestic Pipe		X	Good Condition
83	Canvas Tape on HVAC		X	Good Condition
85	Low-Pressure Steam Pipe		X	Good Condition
86	Hi-Pressure Steam Pipe		X	Good Condition
87	Fitting on Water Make-up		X	Good Condition
89	East Water Tank		X	Good Condition
90	Grey Thermal System Insulation		X	Good Condition
91	HVAC Corner		X	Good Condition
92	Grey Condensate Return		X	Good Condition
93	Fitting on Water Supply (Yellow)		X	Good Condition
94	Fitting on Chiller Thermal System Insulation		X	Good Condition
95	Fittings on Cold Water Pumps		X	Good Condition
96	Fitting on Drain Pipes		X	Good Condition
97	Fittings on Hot Water Pumps		X	Good Condition
98	Condenser Body		X	Good Condition
99	Cooler Body		X	Good Condition
100	Fittings on Cold Water to Coolers		X	Good Condition
101	Boiler Flue		X	Good Condition
102	Fittings on Boiler Water Feeder Pipes		X	Good Condition
103	Valve Header (Orange)		X	Good Condition
104	Small Grey Tank		X	Good Condition
105	Fittings associated with Small Grey Tank		X	Good Condition

*Asbestos containing thermal insulation and red duct caulk are present above existing ceiling (Exact locations not shown on drawing)

*Locations of materials updated for this 2015 Reinspection

LEGEND:
Material Symbol LOCATIONS OF ASBESTOS CONTAINING MATERIAL

PROJECT NAME:

RICHARD J. DALEY CENTER
50 W. WASHINGTON STREET
CHICAGO, ILLINOIS 60602

PREPARED FOR:

50 W. WASHINGTON STREET
SUITE 1203
CHICAGO, ILLINOIS 60602

SHEET NAME:
2015 ASBESTOS REINSPECTION - LOWER LEVEL
INSPECTED BY: James Lehnhardt
IDPH LICENSE #: 100-04208
DRAWN BY: Emine Bushra Boztepe

PREPARED BY:
Carnow, Conibear & Assoc., Ltd.
Environmental Consulting Services
300 W. Adams St., Suite 1200, Chicago, IL 60606
t: 312.782.4486 f: 312.782.5145
www.ccailld.com



CCA PROJECT NUMBER
A13367-0096
REINSPECTION DATE
DECEMBER, 2015
LOWER LEVEL


Summary of Asbestos Bulk Sampling - Concourse Level

Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
1	Terrazzo	MISC	NO	Concourse Level-Throughout Hallways and Vestibules.	X			Good Condition	
3	12" x 12" Black with White Specks Floor Tile	MISC	NO	Concourse Level-Variou Hallways and Offices.		X		Good Condition	
4	Mastic on 12" x 12" Black with White Specks Floor Tile	MISC	NO	Concourse Level-Variou Hallways and Offices.		X		Good Condition	
5	2' x 2' Marble Floor Tile	MISC	NO	Concourse Level-99 Break Room and 99-M.			X	N/A	
6	Mastic 2' x 2' Marble Floor Tile	MISC	NO	Concourse Level-99 Break Room and 99-M.			X	N/A	
7	2' x 2' Computer Flooring	MISC	NO	Concourse Level-Computer Room.			X	N/A	
13	Carpet Mastic	MISC	NO	Concourse Level-Throughout Floor.			X	N/A	
17	Adhesive on 4" Black Vinyl Baseboard	MISC	NO	Concourse Level-Throughout Floor.			X	N/A	
19	1' x 1' Ceiling Tile	MISC	YES	Concourse Level-Main Hallway.			X	N/A	
22	2' x 2' Ceiling Tile	MISC	YES	Concourse Level-Variou Areas Throughout Floor.			X	N/A	
23	2' x 4' Ceiling Tile	MISC	YES	Concourse Level-Variou Areas Throughout Floor.			X	N/A	
24	Plaster	SURF	YES	Concourse Level-Throughout Floor.			X	N/A	
26	Plaster (Ceiling)	SURF	YES	Concourse Level-Throughout Floor.			X	N/A	
27	Drywall/Joint Compound	MISC	YES	Concourse Level-Throughout Floor.			X	N/A	
28	Textured Paint	MISC	YES	Concourse Level-Court Rooms.			X	N/A	
36	Spray-On (Under Stairs)	SURF	YES	Concourse Level-Under Stairs in CL-25Q.			X	N/A	
44	Pink Fire Stop	MISC	YES	Concourse Level-Electrical Closets.			X	N/A	
48	Sink Undercoating (Grey)	MISC	NO	Concourse Level-Break Rooms.			X	N/A	
63	Red Duct Caulk	MISC	NO	Concourse Level-Throughout Floor Above Drop Ceilings.		X		Good Condition	
67	Tank Sealant	MISC	NO	Concourse Level-Planter Areas.			X	N/A	
68	Sealant on Pipe	MISC	NO	Concourse Level-Planter Areas.			X	N/A	

Summary of Asbestos Bulk Sampling - Concourse Level

Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
72	Black Tar Coat on Stairs	MISC	NO	Concourse Level-Under Stairs in CL-25Q.			X	N/A	
73	Caulk (White)	MISC	NO	Concourse Level-Under Stairs in CL-25Q.			X	N/A	
76	Fittings on Fiberglass Pipe Insulation	TSI	YES	Concourse Level-Throughout Floor Above Drop Ceilings.		X		Good Condition	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.
90	Grey Pipe Run	TSI	YES	Concourse Level-Mechanical Space		X		Good Condition	
91	HVAC Corner (Duct Insulation)	TSI	YES	Concourse Level-Boiler Room and HVAC Hallway.	X			Good Condition	
107	City Water Supply	TSI	YES	Concourse Level-Mechanical Space		X		Good Condition	
108	Yellow Tank	TSI	YES	Concourse Level-Mechanical Space			X	N/A	
109	Domestic Hot Water Return	TSI	YES	Concourse Level-Mechanical Space		X		Good Condition	
110	Domestic Hot Water Supply	TSI	YES	Concourse Level-Mechanical Space		X		Good Condition	
111	Cooling Water Pipe	TSI	YES	Concourse Level-Mechanical Space		X		Good Condition	
112	TSI (Small Sup) Pipe	TSI	YES	Concourse Level-Mechanical Space		X		Good Condition	
113	Thermal System Insulation (Mustard)	TSI	YES	Concourse Level-Mechanical Space		X		Good Condition	
114	Grey Tank	TSI	YES	Concourse Level-Mechanical Space		X		Good Condition	
115	Duct Corner	MISC	NO	Concourse Level-Mechanical Space			X	N/A	

Bold Indicates Asbestos and Assumed Asbestos Containing Materials.



*Locations of materials updated for this 2015 Reinspection

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	1 Terrazzo	X		Good Condition
	3 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	4 Mastic on 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	63 Red Duct Caulk		X	Good Condition
	76 Fittings on Fiberglass Pipe Insulation		X	Good Condition
	90 Grey Pipe Run		X	Good Condition
	91 HVAC Corner (Duct Insulation)	X		Good Condition
	107 City Water Supply		X	Good Condition
	109 Domestic Hot Water Return		X	Good Condition
	110 Domestic Hot Water Supply		X	Good Condition
	111 Cooling Water Pipe		X	Good Condition
	112 TSI (Small Sup) Pipe		X	Good Condition
	113 Thermal System Insulation (Mustard)		X	Good Condition
	114 Grey Tank		X	Good Condition

*Asbestos containing thermal insulation and red duct caulk are present above existing ceiling (Exact locations not shown on drawing)

LEGEND:
 LOCATIONS OF ASBESTOS CONTAINING MATERIAL

PROJECT NAME:

 RICHARD J. DALEY CENTER
 50 W. WASHINGTON STREET
 CHICAGO, ILLINOIS 60602

PREPARED FOR:

 50 W. WASHINGTON STREET
 SUITE 1203
 CHICAGO, ILLINOIS 60602

SHEET NAME:
 2015 ASBESTOS REINSPECTION - CONCOURSE LEVEL
 INSPECTED BY: James Lehnhardt
 IDPH LICENSE #: 100-04208
 DRAWN BY: Emine Bushra Boztepe

PREPARED BY:

 Carnow, Conibear & Assoc., Ltd.
 Environmental Consulting Services
 300 W. Adams St., Suite 1200, Chicago, IL 60606
 t: 312.782.4486 f: 312.782.5145
 www.ccalltd.com

**CARNOW
 CONIBEAR**

CCA PROJECT NUMBER
 A13367-0096
 REINSPECTION DATE
 DECEMBER, 2015
**CONCOURSE
 LEVEL**

Summary of Asbestos Bulk Sampling - Lobby


Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
25	Acoustical Plaster	SURF	YES	Lobby Ceiling	X			Good Condition	
33	Spray-On (Cementitious)	SURF	YES	Mechanical Space above Lobby.	X			Good Condition	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.
53	Interior/Bottom Window Sealant	MISC	NO	Lobby Windows		X		Good Condition	
63	Red Duct Caulk	MISC	NO	Mechanical Space above Lobby.	X			Good Condition	
76	Fittings on Fiberglass Pipe Insulation	TSI	YES	Mechanical Space above Lobby.	X			Good Condition	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.
NA	Exterior/Top Window Sealant	MISC	NO	Lobby Windows			X	N/A	
NA	Exterior/Bottom Window Sealant	MISC	NO	Lobby Windows			X	N/A	

Bold Indicates Asbestos and Assumed Asbestos Containing Materials.

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
25	Acoustical Plaster	X		Good Condition
33	Spray-On (Cementitious)	X		Good Condition
53	Interior/Bottom Window Sealant		X	Good Condition

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
63	Red Duct Caulk	X		Good Condition
76	Fittings on Fiberglass Pipe Insulation	X		Good Condition

*Asbestos containing spray applied fire proofing, thermal insulation and red duct caulk are present above existing ceiling (Exact locations not shown on drawing)



*Locations of materials updated for this 2015 Reinspection

*Entry into interstitial space above existing ceiling requires 16 hour asbestos training, personal protective equipment and compliance with Building's asbestos operation and maintenance plan

LEGEND:
Material Symbol LOCATIONS OF ASBESTOS CONTAINING MATERIAL

PROJECT NAME:

RICHARD J. DALEY CENTER
50 W. WASHINGTON STREET
CHICAGO, ILLINOIS 60602

PREPARED FOR:

50 W. WASHINGTON STREET
SUITE 1203
CHICAGO, ILLINOIS 60602

SHEET NAME:
2015 ASBESTOS REINSPECTION - LOBBY
INSPECTED BY: James Lehnhardt
IDPH LICENSE #: 100-04208
DRAWN BY: Emine Bushra Boztepe

PREPARED BY:
Carnow, Conibear & Assoc., Ltd.
Environmental Consulting Services
300 W. Adams St., Suite 1200, Chicago, IL 60606
t: 312.782.4486 f: 312.782.5145
www.ccalltd.com



CCA PROJECT NUMBER
A13367-0096
REINSPECTION DATE
DECEMBER, 2015

LOBBY







Summary of Asbestos Bulk Sampling - 2nd Floor






Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
1	Terrazzo	MISC	NO	2nd Floor-Main Corridors, Private and Freight Elevator Lobbies.	X			Good Condition	
3	12" x 12" Black with White Specks Floor Tile	MISC	NO	2nd Floor-200 Break Room and 200 Storage Rooms.		X		Good Condition	
4	Mastic on 12" x 12" Black with White Specks Floor Tile	MISC	NO	2nd Floor-200 Break Room and 200 Storage Rooms.		X		Good Condition	
14	Carpet Mastic with Black Mastic underneath	MISC	NO	2nd Floor-Office Areas.		X		Good Condition	
18	1' x 1' Spline Ceiling Tile	MISC	YES	2nd Floor-Throughout Floor.			X	N/A	
24	Plaster	SURF	YES	2nd Floor-Throughout Floor.			X	N/A	
27	Drywall/Joint Compound	MISC	YES	2nd Floor-Various Office Areas			X	N/A	
33	Spray-On (Cementitious)	SURF	YES	2nd Floor-On I-Beams Above the Drop Ceiling Throughout Floor Including Electrical Closets.		X		Slight Damage-Debris	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.
40	Canvas Flex Duct	MISC	NO	2nd Floor-Inside Unit Vents Around the Perimeter of the Floor.			X	N/A	
41	Red Sealant on Canvas Duct	MISC	NO	2nd Floor-Inside Unit Vents Around the Perimeter of the Floor.		X		Good Condition	
42	Grey Cementitious Board	MISC	NO	2nd Floor-250 B.		X		Physical Damage	Repair or Remove. Label as ACM
43	Electrical Floor Board	MISC	YES	2nd Floor-Electrical Closets.		X		Slight Damage	Repair or Remove. Label as ACM
44	Pink Fire Stop	MISC	YES	2nd Floor-Electrical Closets.			X	N/A	
45	White Fire Stop	MISC	YES	2nd Floor-Electrical Closets.			X	N/A	
48	Sink Undercoating (White and Grey)	MISC	NO	2nd Floor-200 Break Room and in 200 Hallways.			X	N/A	

Summary of Asbestos Bulk Sampling - 2nd Floor


Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
53	Window Glaze	MISC	NO	2nd Floor-Around the Inside Perimeter of the Large Windows.			X	N/A	
54	Window Frame Caulk	MISC	NO	2nd Floor-Around the Outside Perimeter of the Large Windows.	X			Good Condition	
55	Small Window Glaze	MISC	NO	2nd Floor-Stairwell # 3.	X			Good Condition	
57	Red Caulk	MISC	NO	2nd Floor-Electrical Closets.			X	N/A	
76	Fitting on Fiberglass Pipe Insulation	TSI	YES	2nd Floor-Pipe Chase and Above Drop Ceiling throughout.		X		Good Condition	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.
77	Misc. Insulation (Stuffed around pipe)	MISC	YES	2nd Floor-250 B.			X	N/A	

Bold Indicates Asbestos and Assumed Asbestos Containing Materials

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	1 Terrazzo	X		Good Condition
	3 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	4 Mastic on 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	14 Carpet Mastic with Black Mastic underneath		X	Good Condition
	33 Spray-On (Cementitious)		X	Slight Damage-Debris
	41 Red Sealant on Canvas Duct		X	Good Condition

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	42 Grey Cementitious Board		X	Physical Damage
	43 Electrical Floor Board		X	Slight Damage
	54 Window Frame Caulk	X		Good Condition
	55 Small Window Glaze	X		Good Condition
	76 Fitting on Fiberglass Pipe Insulation		X	Good Condition

*Asbestos containing spray applied fire proofing and thermal insulation are present above existing ceiling (Locations not shown on drawing)



*Locations of materials updated for this 2015 Reinspection

*Entry into interstitial space above existing ceiling requires 16 hour asbestos training, personal protective equipment and compliance with Building's asbestos operation and maintenance plan

LEGEND:

Material Symbol LOCATIONS OF ASBESTOS CONTAINING MATERIAL

PROJECT NAME:



RICHARD J. DALEY CENTER
50 W. WASHINGTON STREET
CHICAGO, ILLINOIS 60602

PREPARED FOR:



50 W. WASHINGTON STREET
SUITE 1203
CHICAGO, ILLINOIS 60602

SHEET NAME:

2015 ASBESTOS REINSPECTION - 2ND FLOOR

INSPECTED BY: James Lehnhardt

IDPH LICENSE #: 100-04208

DRAWN BY: Emine Bushra Boztepe

PREPARED BY:

Carnow, Conbear & Assoc., Ltd.
Environmental Consulting Services
300 W. Adams St., Suite 1200, Chicago, IL 60606
T: 312.782.4488 F: 312.782.5145
www.ccailld.com



CCA PROJECT NUMBER

A13367-0096

REINSPECTION DATE

DECEMBER, 2015

2ND FLOOR






Summary of Asbestos Bulk Sampling - 3rd Floor






Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
1	Terrazzo	MISC	NO	3rd Floor-Main Corridors, Private and Frieght Elevator Lobbies.	X			Good Condition	
3	12" x 12" Black with White Specks Floor Tile	MISC	YES	3rd Floor-312 Copy Center, 350, Storage Room 356 B, and Office area in 317.		X		Good Condition	
4	Mastic on 12" x 12" Black with White Specks Floor Tile	MISC	NO	3rd Floor-312 Copy Center, 350, Storage Room 356 B, and Office area in 317.		X		Good Condition	
13	Carpet Mastic	MISC	NO	3rd Floor-Office Areas.			X	N/A	
16	Vinyl 4" Black Baseboard	TSI	YES	3rd Floor-Women's Washroom Vestibule			X	N/A	
17	Mastic on Vinyl 4" Black Baseboard	TSI	YES	4th Floor-Women's Washroom Vestibule			X	N/A	
18	1' x 1' Spline Ceiling Tile	MISC	YES	3rd Floor-Throughout Floor.			X	N/A	
24	Plaster	SURF	YES	3rd Floor-Throughout Floor.			X	N/A	
27	Drywall/Joint Compound	MISC	NO	3rd Floor-Various Office Areas.			X	N/A	
33	Spray-On (Cementitious)	MISC	YES	3rd Floor-On I-Beams Above the Drop Ceiling Throughout Floor Including Electrical Closets.		X		Slight Damage - Debris	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.
40	Canvas Flex Duct	MISC	NO	3rd Floor-Inside Unit Vents Around the Perimeter of the Floor.			X	N/A	
41	Red Sealant on Canvas Duct	MISC	NO	3rd Floor-Inside Unit Vents Around the Perimeter of the Floor.		X		Good Condition	
42	Grey Cementitious Board (Ceiling)	MISC	YES	3rd Floor-350 B.		X		Physical Damage	Repair or Remove. Label as ACM
43	Electrical Floor Board	SURF	YES	3rd Floor-Electrical Closets and Telephone Closet North		X		Slight Damage	Repair or Remove. Label as ACM.

Summary of Asbestos Bulk Sampling - 3rd Floor


Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
44	Pink Fire Stop	MISC	NO	3rd Floor-Electrical Closets.			X	N/A	
47	Electrical Tape (White)	MISC	YES	3rd Floor-Telephone Closet South.			X	N/A	
53	Window Glaze	MISC	NO	3rd Floor-Around the Inside Perimeter of the Large Windows.			X	N/A	
54	Window Frame Caulk	MISC	NO	3rd Floor-Around the Outside Perimeter of the Large Windows.	X			Good Condition	
55	Small Window Glaze	MISC	NO	3rd Floor-Stairwell #3.		X		Good Condition	
57	Red Caulk	MISC	NO	3rd Floor-Electrical Closets			X	N/A	
58	Black Sealant	MISC	NO	3rd Floor-Electrical Closets .			X	N/A	
76	Fitting on Fiberglass Pipe Insulation	MISC	YES	3rd Floor-Pipe Chases and Above the Drop Ceiling Throughout.	X			Good Condition	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.

Bold Indicates Asbestos and Assumed Asbestos Containing Materials.

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	1 Terrazzo	X		Good Condition
	3 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	4 Mastic on 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	33 Spray-On (Cementitious)		X	Slight Damage-Debris
	41 Red Sealant on Canvas Duct		X	Good Condition

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	42 Grey Cementitious Board		X	Physical Damage
	43 Electrical Floor Board		X	Slight Damage
	54 Window Frame Caulk	X		Good Condition
	55 Small Window Glaze		X	Good Condition
	76 Fitting on Fiberglass Pipe Insulation	X		Good Condition

*Asbestos containing spray applied fire proofing and thermal insulation are present above existing ceiling (Locations not shown on drawing)



*Locations of materials updated for this 2015 Reinspection

*Entry into interstitial space above existing ceiling requires 16 hour asbestos training, personal protective equipment and compliance with Building's asbestos operation and maintenance plan

LEGEND:

 LOCATIONS OF ASBESTOS CONTAINING MATERIAL

PROJECT NAME:



RICHARD J. DALEY CENTER

50 W. WASHINGTON STREET
CHICAGO, ILLINOIS 60602

PREPARED FOR:



50 W. WASHINGTON STREET
SUITE 1203
CHICAGO, ILLINOIS 60602

SHEET NAME:

2015 ASBESTOS REINSPECTION - 3RD FLOOR

INSPECTED BY: James Lehnhardt

IDPH LICENSE #: 100-04208

DRAWN BY: Emine Bushra Boztepe

PREPARED BY:

Carnow, Conibear & Assoc., Ltd.
Environmental Consulting Services
300 W. Adams St., Suite 1200, Chicago, IL 60606
t: 312.782.4486 f: 312.782.5145
www.ccailld.com



CCA PROJECT NUMBER
A13367-0096

REINSPECTION DATE
DECEMBER, 2015

3RD FLOOR

Summary of Asbestos Bulk Sampling - 4th Floor

Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
1	Terrazzo	MISC	NO	4th Floor-Freight Elevator and Private Elevator Lobbies	X			Good Condition	
2	Terrazzo (New)	MISC	NO	4th Floor-Main Corridors	X			Good Condition	
3	12" x 12" Black with White Specs Floor Tile	MISC	NO	4th Floor-Break Room.			X	N/A	
4	Mastic on 12" x 12" Black with White Specks Floor Tile	MISC	NO	4th Floor-Break Room			X	N/A	
13	Carpet Mastic	MISC	NO	4th Floor-Courtrooms, Perimeter Hallways and Offices Areas			X	N/A	
16	4" Black Vinyl Baseboard	MISC	NO	4th Floor-Break Room			X	N/A	
17	Adhesive on 4" Black Vinyl Baseboard	MISC	NO	4th Floor-Break Room			X	N/A	
18	1' x 1' Spline Ceiling Tile	MISC	YES	4th Floor-Throughout Floor			X	N/A	
24	Plaster	SURF	NO	4th Floor-Center Elevator Area			X	N/A	
27	Drywall/Joint Compound	MISC	YES	4th Floor-Courtrooms and Perimeter Offices			X	N/A	
28	Textured Paint	MISC	NO	4th Floor-Courtrooms (Wall behind Judge's Chair)			X	N/A	
29	Wall Mortar	MISC	NO	4th Floor-Electrical Closet EC-C			X	N/A	
30	Concrete Wall Seam	MISC	NO	4th Floor-Electrical Closets			X	N/A	
31	Tape on Concret Wall Seam	MISC	NO	4th Floor-Electrical Closets			X	N/A	
33	Spray-On (Cementitious)	SURF	YES	4th Floor-I-Beams in Electrical Closets		X		Slight Damage	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.
34	Spray-On (Fluffy)	SURF	YES	4th Floor-On I-Beams Above Drop Ceilings. (Overspray was Identified on Ceiling Deck and Ducts around I-Beams)			X	N/A	
40	Canvas Flex Duct	MISC	NO	4th Floor-Inside Perimeter Unit Vents.			X	N/A	

Summary of Asbestos Bulk Sampling - 4th Floor

Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
41	Red Sealant on Canvas Duct	MISC	NO	4th Floor-Inside Perimeter Unit Vents. (Material was Identified on Flex Duct and Unit Vent)		X		Good Condition	
42	Grey Cementitious Board	MISC	NO	4th Floor-Conveyor Room	X			Physical Damage	Repair or Remove. Label as ACM
43	Electrical Floor Board	MISC	YES	4th Floor-Electrical Closets on the Floor by Pipes		X		Slight Damage	Repair or Remove. Label as ACM
44	Pink Fire Stop	MISC	YES	4th Floor-Electrical Closets on the Floor by Pipes			X	N/A	
46	Grey Fire Stop	MISC	NO	4th Floor-Electrical Closets on Walls			X	N/A	
47	Electrical Tape	MISC	NO	4th Floor-Electrical Closets on Electrical Pipes			X	N/A	
48	Sink Undercoating (Black)	MISC	YES	4th Floor-Break Room			X	N/A	
53	Window Glaze	MISC	NO	4th Floor-Perimeter Windows			X	N/A	Material sampled 2015
54	Window Frame Caulk	MISC	NO	4th Floor-Perimeter Windows		X		Good Condition	
55	Small Window Glaze	MISC	NO	4th Floor-Stairwell #3	X			Good Condition	
56	Mortar around Windows	MISC	YES	4th Floor-Under Window in the Southeast Window Bay			X	N/A	
57	Red Caulk	MISC	NO	4th Floor-Electrical Closets around Pipes			X	N/A	
59	Gap Sealant (Fire Hose Cabinet)	MISC	YES	4th Floor-Around Fire Hose Cabinet in the Main Corridor by Courtroom 401			X	N/A	
61	Grey Sealant on Pipe	MISC	NO	4th Floor-Above Ceilings on Metal Pipes			X	N/A	
62	Brown Sealant on Pipe	MISC	NO	4th Floor-Above Ceilings on Metal Pipes			X	N/A	

Summary of Asbestos Bulk Sampling - 4th Floor

Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
76	Fittings on Fiberglass Pipe Insulation	TSI	YES	4th Floor-Pipe Chase and Above Drop Ceiling Throughout.	X			Good Condition	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.
78	Seam Tape on Fiberglass Pipe Insulation	TSI	NO	4th Floor-Above Ceilings Throughout Floor			X	N/A	
79	Debris in Washroom Access Panel	MISC	YES	4th Floor-Inside Washroom Access Panels (Material Looked like it may have been overspray from Spray-On (Fluffy))			X	N/A	

Bold Indicates Asbestos and Assumed Asbestos Containing Materials






Summary of Asbestos Bulk Sampling - 5th Floor





Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
1	Terrazzo	MISC	NO	5th Floor-Main Corridors, Private and Freight Elevator Lobbies.	X			Good Condition	
3	12" x 12" Black with White Floor Tile	MISC	NO	5th Floor-Variou Rooms			X	N/A	
4	Mastic on 12" x 12" Black with White Floor Tile	MISC	NO	5th Floor-Variou Rooms		X		Good Condition	
8	12" x 12" Tan Floor Tile	MISC	NO	5th Floor-Center Corridor under rolling book shelves.			X	N/A	
9	Mastic on 12" x 12" Tan Floor Tile	MISC	NO	5th Floor-Center Corridor under rolling book shelves.			X	N/A	
14	Carpet Mastic with Black Mastic Underneath	MISC	NO	5th Floor-Office Areas. Black Mastic from old floor tile still present on floor.		X		Good Condition	
16	4" Black Vinyl Baseboard	MISC	NO	5th Floor-Variou Rooms			X	N/A	
17	Adhesive on 4" Black Baseboard	MISC	NO	5th Floor-Variou Rooms			X	N/A	
18	1' x 1' Spline Ceiling Tile	MISC	YES	5th Floor-Throughout Floor.			X	N/A	
24	Plaster	SURF	YES	5th Floor-Throughout Floor.			X	N/A	
27	Drywall/Joint Compound	MISC	YES	5th Floor-Office Areas.			X	N/A	
32	Wall Patch Material	SURF	NO	5th Floor-Telephone Closet North			X	N/A	
33	Spray-On (Cementitious)	SURF	YES	5th Floor-On I-Beams Above the Drop Ceiling Throughout Floor Including Electrical Closets.		X		Slight Damage - Debris	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.
40	Canvas on Flex Duct	MISC	NO	5th Floor-Inside Unit Vents Around the Perimeter of the Floor.			X	N/A	
41	Red Sealant on Canvas Duct	MISC	NO	5th Floor-Inside Unit Vents Around the Perimeter of the Floor.			X	N/A	
42	Grey Cementitious Board	MISC	NO	5th Floor-Room 550 B.		X		Physical Damage	Repair or Remove. Label as ACM

Summary of Asbestos Bulk Sampling - 5th Floor


Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
43	Electrical Floor Board	MISC	YES	5th Floor-Electrical Closets		X		Slight Damage	Repair or Remove. Label as ACM
44	Pink Fire Stop	MISC	YES	5th Floor-Electrical Closets			X	N/A	
48	Sink Undercoating (White)	MISC	NO	5th Floor-Room 527.			X	N/A	
53	Window Glaze	MISC	NO	5th Floor-Around the Inside Perimeter on the Large Windows.			X	N/A	
54	Window Frame Caulk	MISC	NO	5th Floor-Around the Outside Perimeter on the Large Windows.		X		Good Condition	
55	Small Window Glaze	MISC	NO	5th Floor-Stairwell #3		X		Good Condition	
57	Red Caulk	MISC	NO	5th Floor-Electrical Closets			X	N/A	
76	Fittings on Fiberglass Pipe Insulation	TSI	YES	5th Floor-Pipe Chase and Above Drop Ceiling Throughout.	X			Good Condition	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.

Bold Indicates Asbestos and Assumed Asbestos Containing Materials.

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	1 Terrazzo	X		Good Condition
	4 Mastic on 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	14 Carpet Mastic with Black Mastic underneath		X	Good Condition
	33 Spray-On (Cementitious)		X	Slight Damage-Debris
	42 Grey Cementitious Board		X	Physical Damage

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	43 Electrical Floor Board		X	Slight Damage
	54 Window Frame Caulk		X	Good Condition
	55 Small Window Glaze		X	Good Condition
	76 Fitting on Fiberglass Pipe Insulation	X		Good Condition

*Asbestos containing spray applied fire proofing and thermal insulation are present above existing ceiling (Exact locations not shown on drawing)



*Locations of materials updated for this 2015 Reinspection

*Entry into interstitial space above existing ceiling requires 16 hour asbestos training, personal protective equipment and compliance with Building's asbestos operation and maintenance plan

LEGEND:  LOCATIONS OF ASBESTOS CONTAINING MATERIAL	PROJECT NAME:  RICHARD J. DALEY CENTER 50 W. WASHINGTON STREET CHICAGO, ILLINOIS 60602	PREPARED FOR:  50 W. WASHINGTON STREET SUITE 1203 CHICAGO, ILLINOIS 60602	SHEET NAME: 2015 ASBESTOS REINSPECTION - 5TH FLOOR	PREPARED BY: Carnow, Conibear & Assoc., Ltd. Environmental Consulting Services 300 W. Adams St., Suite 1200, Chicago, IL 60606 t: 312.782.4486 f: 312.782.5145 www.ccailld.com	CCA PROJECT NUMBER A13367-0096
			INSPECTED BY: James Lehnhardt IDPH LICENSE #: 100-04208 DRAWN BY: Emine Bushra Boztepe		REINSPECTION DATE DECEMBER, 2015



5TH FLOOR






Summary of Asbestos Bulk Sampling - 6th Floor






Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
1	Terrazzo	MISC	NO	6th Floor-Main Corridors, Private and Freight Elevator Lobbies.	X			Good Condition	
3	12" x 12" Black with White Specks Floor Tile	MISC	NO	6th Floor-Room 600, Throughout 601 and 602, and Room 650 A.		X		Good Condition	Partial Abatement September 2011
4	Mastic on 12" x 12" Black with White Specks Floor Tile	MISC	NO	6th Floor-Room 600, Throughout 601 and 602, and Room 650 A.		X		Good Condition	
13	Carpet Mastic	MISC	NO	6th Floor-Rooms 601 A and 602 A.			X	N/A	
18	1' x 1' Spline Ceiling Tile	MISC	YES	6th Floor-Throughout Floor.			X	N/A	
24	Plaster	SURF	YES	6th Floor-Throughout Floor.			X	N/A	
32	Wall Patch Material	SURF	NO	6th Floor-Electrical Closet A.			X	N/A	
33	Spray-On (Cementitious)	SURF	YES	6th Floor-On Ibeams Above the Drop Ceiling Throughout Floor Including Electrical Closets.		X		Slight Damage - Debris	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.
40	Canvas Flex Duct	MISC	NO	6th Floor-Inside Perimeter Unit Vents.			X	N/A	
41	Red Sealant on Canvas Duct	MISC	NO	6th Floor-Inside Perimeter Unit Vents.		X		Good Condition	
42	Grey Cementitious Board	MISC	NO	6th Floor-Room 650 B.	X			Physical Damage	Repair or Remove. Label as ACM.
43	Electrical Floor Board	MISC	YES	6th Floor-Electrical Closets and Telephone Room North.		X		Slight Damage	Repair or Remove. Label as ACM.
44	Pink Fire Stop	MISC	YES	6th Floor-Electrical Closets and Telephone Room North.			X	N/A	
53	Window Glaze	MISC	NO	6th Floor-Around the Inside Perimeter of the Large Windows.			X	N/A	
54	Window Frame Caulk	MISC	NO	6th Floor-Around the Outside Perimeter of the Large Windows.	X			Good Condition	
55	Small Window Glaze	MISC	NO	6th Floor-Strairwell # 3.		X		Good Condition	

Summary of Asbestos Bulk Sampling - 6th Floor


Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
57	Red Caulk	MISC	NO	6th Floor-Electrical Closets and Telephone Room North.			X	N/A	
76	Fitting on Fiberglass Pipe Insulation	TSI	YES	6th Floor-Pipe Chases and Above Drop Ceilings Throughout.	X			Good Condition	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.

Bold Indicates Asbestos and Assumed Asbestos Containing Materials.

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	1 Terrazzo	X		Good Condition
	3 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	4 Mastic on 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	33 Spray-On (Cementitious)		X	Slight Damage-Debris
	41 Red Sealant on Canvas Duct		X	Good Condition

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	42 Grey Cementitious Board	X		Physical Damage
	43 Electrical Floor Board		X	Slight Damage
	54 Window Frame Caulk	X		Good Condition
	55 Small Window Glaze		X	Good Condition
	76 Fitting on Fiberglass Pipe Insulation	X		Good Condition

*Asbestos containing spray applied fire proofing and thermal insulation are present above existing ceiling (Exact locations not shown on drawing)



*Locations of materials updated for this 2015 Reinspection

*Entry into interstitial space above existing ceiling requires 16 hour asbestos training, personal protective equipment and compliance with Building's asbestos operation and maintenance plan

LEGEND:  LOCATIONS OF ASBESTOS CONTAINING MATERIAL	PROJECT NAME:  RICHARD J. DALEY CENTER 50 W. WASHINGTON STREET CHICAGO, ILLINOIS 60602	PREPARED FOR:  50 W. WASHINGTON STREET SUITE 1203 CHICAGO, ILLINOIS 60602	SHEET NAME: 2015 ASBESTOS REINSPECTION - 6TH FLOOR	PREPARED BY: Carnow, Conibear & Assoc., Ltd. Environmental Consulting Services 300 W. Adams St., Suite 1200, Chicago, IL 60606 t: 312.782.4486 f: 312.782.5145 www.ccailld.com	CCA PROJECT NUMBER A13367-0096
			INSPECTED BY: James Lehnhardt IDPH LICENSE #: 100-04208 DRAWN BY: Emine Bushra Boztepe		REINSPECTION DATE DECEMBER, 2015



6TH FLOOR






Summary of Asbestos Bulk Sampling - 7th Floor






Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
1	Terrazzo	MISC	NO	7th Floor-Main Corridors, Private and Freight Elevator Lobbies.	X			Good Condition	
3	12" x 12" Black with White Specks Floor Tile	MISC	NO	7th Floor-Rooms 701, 702, 702 A, 706, 750 A, and Southeast Janitor's Closet.		X		Good Condition	Partial Abatement March 2014
4	Mastic on 12" x 12" Black with White Specks Floor Tile	MISC	NO	7th Floor-Rooms 701, 702, 702 A, 706, 750 A, and Southeast Janitor's Closet.		X		Good Condition	
13	Carpet Mastic	MISC	NO	7th Floor-Rooms 701 B thru 701 F, 705 A, B & C, and 702 N.			X	N/A	
18	1' x 1' Spline Ceiling Tile	MISC	YES	7th Floor-Throughout Floor.			X	N/A	
27	Plaster	SURF	YES	7th Floor-Throughout Floor.			X	N/A	
32	Wall Patch Material	SURF	NO	7th Floor-Electrical Closet A.		X		Not Observed	
33	Spray-On (Cementitious)	SURF	YES	7th Floor-On I-Beams Above the Drop Ceiling Throughout Floor Including Electrical Closets.		X		Slight Damage - Debris	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.
40	Canvas Flex Duct	MISC	NO	7th Floor-Inside Perimeter Unit Vents.			X	N/A	
41	Red Sealant on Canvas Duct	MISC	NO	7th Floor-Inside Perimeter Unit Vents.		X		Good Condition	
42	Grey Cementitious Board	MISC	NO	7th Floor-Room 750 B		X		Physical Damage	Repair or Remove. Label as ACM
43	Electrical Floor Board	MISC	YES	7th Floor-Electrical Closets and Telephone Closet North.		X		Slight Damage	Repair or Remove. Label as ACM
44	Pink Fire Stop	MISC	YES	7th Floor-Electrical Closets and Telephone Closet North.				Not Observed	
53	Window Glaze	MISC	NO	7th Floor-Around the Inside Perimeter of the Large Windows.			X	N/A	

Summary of Asbestos Bulk Sampling - 7th Floor


Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
54	Window Frame Caulk	MISC	NO	7th Floor-Around the Outside Perimeter of the Large Windows.	X			Good Condition	
55	Small Window Glaze	MISC	NO	7th Floor-Stairwell # 3		X		Good Condition	
57	Red Caulk	MISC	NO	7th Floor-Electrical Closets and Telephone Closet South.			X	N/A	
76	Fitting on Fiberglass Pipe Insulation	TSI	YES	7th Floor-Pipe Chases and Above the Drop Ceiling Throughout.	X			Good Condition	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.

Bold Indicates Asbestos and Assumed Asbestos Containing Materials.

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	1 Terrazzo	X		Good Condition
	3 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	4 Mastic on 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	33 Spray-On (Cementitious)		X	Slight Damage-Debris
	41 Red Sealant on Canvas Duct		X	Good Condition

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	42 Grey Cementitious Board		X	Physical Damage
	43 Electrical Floor Board		X	Slight Damage
	54 Window Frame Caulk	X		Good Condition
	55 Small Window Glaze		X	Good Condition
	76 Fitting on Fiberglass Pipe Insulation	X		Good Condition

*Asbestos containing spray applied fire proofing and thermal insulation are present above existing ceiling (Exact locations not shown on drawing)



*Locations of materials updated for this 2015 Reinspection

*Entry into interstitial space above existing ceiling requires 16 hour asbestos training, personal protective equipment and compliance with Building's asbestos operation and maintenance plan

LEGEND:  LOCATIONS OF ASBESTOS CONTAINING MATERIAL	PROJECT NAME:  RICHARD J. DALEY CENTER 50 W. WASHINGTON STREET CHICAGO, ILLINOIS 60602	PREPARED FOR:  50 W. WASHINGTON STREET SUITE 1203 CHICAGO, ILLINOIS 60602	SHEET NAME: 2015 ASBESTOS REINSPECTION - 7TH FLOOR INSPECTED BY: James Lehnhardt IDPH LICENSE #: 100-04208 DRAWN BY: Emine Bushra Boztepe	PREPARED BY:  Carnow, Conibear & Assoc., Ltd. Environmental Consulting Services 300 W. Adams St., Suite 1200, Chicago, IL 60606 t: 312.782.4486 f: 312.782.5145 www.ccailld.com	CCA PROJECT NUMBER A13367-0096 REINSPECTION DATE DECEMBER, 2015 7TH FLOOR
---	---	--	---	---	--






Summary of Asbestos Bulk Sampling - 8th Floor






Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
1	Terrazzo	MISC	NO	8th Floor-Main Corridor, Private and Freight Elevator Lobbies.	X			Good Condition	
3	12" x 12" Black with White Specks Floor Tile	MISC	NO	8th Floor-Rooms 801, 802, and 850 A.		X		Good Condition	
4	Mastic on 12" x 12" Black with White Specks Floor Tile	MISC	NO	8th Floor-Rooms 801, 802, and 850 A.		X		Good Condition	
13	Carpet Mastic	MISC	NO	8th Floor-Rooms 801 A & B and 802 A & B.			X	N/A	
18	1' x 1' Spline Ceiling Tile	MISC	YES	8th Floor-Throughout Floor.			X	N/A	
24	Plaster	SURF	YES	8th Floor-Throughout Floor.			X	N/A	
33	Spray-On (Cementitious)	MISC	YES	8th Floor-On I-Beams Above the Drop Ceiling Throughout the Floor, Including Electrical Closets.		X		Slight Damage - Debris	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.
40	Canvas Flex Duct	MISC	NO	8th Floor-Inside Perimeter Unit Vents.			X	N/A	
41	Red Sealant on Canvas Flex Duct	MISC	NO	8th Floor-Inside Perimeter Unit Vents.		X		Good Condition	
42	Grey Cementitious Board (Ceiling)	MISC	NO	8th Floor-Room 850 B.		X		Physical Damage	Repair or Remove. Label as ACM
43	Electrical Floor Board	SURF	YES	8th Floor-Electrical Closets.		X		Slight Damage	Repair or Remove. Label as ACM
44	Pink Fire Stop	MISC	NO	8th Floor-Electrical Closets.			X	N/A	
53	Window Glaze	MISC	NO	8th Floor-Around the Inside of the Perimeter Large Windows.			X	N/A	
54	Window Frame Caulk	MISC	NO	8th Floor-Around the Outside of the Perimeter Large Windows.	X			Good Condition	
55	Small Window Glaze	MISC	YES	8th Floor-Stairwell # 3.		X		Good Condition	

Summary of Asbestos Bulk Sampling - 8th Floor


Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
57	Red Caulk	MISC	YES	8th Floor-Electrical Closets and Telephone Rooms.			X	N/A	
76	Fitting on Fiberglass Pipe Insulation	MISC	NO	8th Floor-Pipe Chases and Above Drop Ceilings Throughout Floor.	X			Good Condition	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.

Bold Indicates Asbestos and Assumed Asbestos Containing Materials.

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	1 Terrazzo	X		Good Condition
	3 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	4 Mastic on 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	33 Spray-On (Cementitious)		X	Slight Damage-Debris
	41 Red Sealant on Canvas Duct		X	Good Condition

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	42 Grey Cementitious Board		X	Physical Damage
	43 Electrical Floor Board		X	Slight Damage
	54 Window Frame Caulk	X		Good Condition
	55 Small Window Glaze		X	Good Condition
	76 Fitting on Fiberglass Pipe Insulation	X		Good Condition

*Asbestos containing spray applied fire proofing and thermal insulation are present above existing ceiling (Exact locations not shown on drawing)



*Locations of materials updated for this 2015 Reinspection

*Entry into interstitial space above existing ceiling requires 16 hour asbestos training, personal protective equipment and compliance with Building's asbestos operation and maintenance plan

LEGEND:  LOCATIONS OF ASBESTOS CONTAINING MATERIAL	PROJECT NAME:  RICHARD J. DALEY CENTER 50 W. WASHINGTON STREET CHICAGO, ILLINOIS 60602	PREPARED FOR:  50 W. WASHINGTON STREET SUITE 1203 CHICAGO, ILLINOIS 60602	SHEET NAME: 2015 ASBESTOS REINSPECTION - 8TH FLOOR	PREPARED BY: Carnow, Conibear & Assoc., Ltd. Environmental Consulting Services 300 W. Adams St., Suite 1200, Chicago, IL 60606 t: 312.782.4486 f: 312.782.5145 www.ccailld.com	CCA PROJECT NUMBER A13367-0096
			INSPECTED BY: James Lehnhardt IDPH LICENSE #: 100-04208 DRAWN BY: Emine Bushra Boztepe		REINSPECTION DATE DECEMBER, 2015



8TH FLOOR








Summary of Asbestos Bulk Sampling - 9th Floor








Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
3	12" x 12" Black with White Specks Floor Tile	MISC	NO	9th Floor - Office areas.		X		Good Condition	
4	Mastic on 12" x 12" Black with White Specks Floor Tile	MISC	NO	9th Floor - Office areas.		X		Good Condition	
11	12" x 12" Black with White Streaks Floor Tile	MISC	NO	9th Floor - Elevator Corp. Office.			X	N/A	
12	Mastic on 12" x 12" Black with White Streaks Floor Tile	MISC	NO	9th Floor - Elevator Corp. Office.			X	N/A	
23	2' x 4' Ceiling Tile	MISC	YES	9th Floor - Office areas.			X	N/A	
24	Plaster	SURF	NO	9th Floor & 9M - Throughout Floors.			X	N/A	
27	Drywall/Joint Compound	MISC	YES	9th Floor - Throughout Floor.			X	N/A	
33	Spray-On (Cementitious)	SURF	YES	9th Floor - Throughout Floor.		X		Slight Damage-Debris	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.
42	Grey Cementitious Board	MISC	NO	9th Floor & 9M - Electrical Closets.		X		Damage-Cracked	Repair or Remove. Label as ACM
43	Electrical Floor Board	MISC	YES	9th Floor - by elevator Bays.		X		Slight Damage	Repair or Remove. Label as ACM
44	Pink Fire Stop	MISC	YES	9th Floor & 9M - by elevator Bays.			X	N/A	
48	Black Sink Undercoating	MISC	NO	9th Floor- Office area.		X		Good Condition	
55	Small Window Glaze	MISC	NO	9th Floor & 9M - Stairwell #3.		X		Good Condition	
65	White Duct Sealant (Floor)	MISC	NO	9th Floor & 9M - Throughout Floors.		X		Good Condition	
74	Red Sealant inside Air Chamber	MISC	NO	9th Floor - Inside Air Chambers.		X		Good Condition	
75	Beige Sealant/Caulk	MISC	NO	9th Floor & 9M - Inside Air Chambers.			X	N/A	
85	Fittings on Lo-Press	TSI	YES	9th Floor - Throughout Floor.		X		Good Condition	
127	Fittings on Chilled Water	TSI	YES	9th Floor - Throughout Floor.		X		Good Condition	
130	Fittings on Fiberglass Domestic Water	TSI	YES	9th Floor - Throughout Floor.		X		Good Condition	
136	Vibration Damper	MISC	NO	9th Floor - Throughout Floor.			X	N/A	

Summary of Asbestos Bulk Sampling - 9th Floor


Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
137	White Tank	TSI	YES	9th Floor - by S-16.		X		Not Observed	
138	Duct Canvas on Fan Housing	TSI	NO	9th Floor - Throughout Floor.		X		Good Condition	
139	Canvas on Supply Blower Unit	TSI	NO	9th Floor - Throughout Floor.		X		Good Condition	
141	Black Wall in Air Handler	TSI	NO	9th Floor - Throughout Floor.			X	N/A	
142	Fittings on Water Cooler	TSI	YES	9th Floor - Throughout Floor.		X		Good Condition	
143	Air Duct Seam Tape	MISC	NO	9th Floor - Throughout Floor.			X	N/A	

Bold Indicates Asbestos and Assumed Asbestos Containing Materials.

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	3 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	4 Mastic on 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	33 Spray-On (Cementitious)		X	Slight Damage-Debris
	43 Electrical Floor Board		X	Slight Damage
	48 Black Sink Undercoating		X	Good Condition
	55 Small Window Glaze		X	Good Condition
	65 White Duct Sealant (Floor)		X	Good Condition

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	74 Red Sealant Inside Air Chamber		X	Good Condition
	85 Fittings on Lo-Press		X	Good Condition
	127 Fittings on chilled Water		X	Good Condition
	130 Fittings on Fiberglass Domestic Water		X	Good Condition
	138 Duct Canvas on Fan housing		X	Good Condition
	139 Canvas on Supply Blower Unit		X	Good Condition
	142 Fittings on Water Cooler		X	Good Condition

*Asbestos containing spray applied fire proofing and thermal insulation are throughout floor.



*Locations of materials updated for this 2015 Reinspection

LEGEND:

 LOCATIONS OF ASBESTOS CONTAINING MATERIAL

PROJECT NAME:



RICHARD J. DALEY CENTER

50 W. WASHINGTON STREET
CHICAGO, ILLINOIS 60602

PREPARED FOR:



50 W. WASHINGTON STREET
SUITE 1203
CHICAGO, ILLINOIS 60602

SHEET NAME:

2015 ASBESTOS REINSPECTION - 9TH FLOOR

INSPECTED BY: James Lehnhardt

IDPH LICENSE #: 100-04208

DRAWN BY: Emine Bushra Boztepe

PREPARED BY:




Carnow, Conibear & Assoc., Ltd.
Environmental Consulting Services
300 W. Adams St., Suite 1200, Chicago, IL 60606
t: 312.782.4486 f: 312.782.5145
www.ccalltd.com




CCA PROJECT NUMBER
A13367-0096

REINSPECTION DATE
DECEMBER, 2015

9TH FLOOR

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	33 Spray-On (Cementitious)		X	Slight Damage
	42 Grey Cementitious Board		X	Damage-Cracked
	55 Small Window Glaze		X	Good Condition

*Asbestos containing spray applied fire proofing, thermal insulation and red duct caulk are present throughout floor.



*Locations of materials updated for this 2015 Reinspection

LEGEND:

Material Symbol

LOCATIONS OF ASBESTOS CONTAINING MATERIAL

PROJECT NAME:



RICHARD J. DALEY CENTER

50 W. WASHINGTON STREET
CHICAGO, ILLINOIS 60602

PREPARED FOR:



50 W. WASHINGTON STREET
SUITE 1203
CHICAGO, ILLINOIS 60602

SHEET NAME:

2015 ASBESTOS REINSPECTION - 9 MECHANICAL FL.

INSPECTED BY: James Lehnhardt

IDPH LICENSE #: 100-04208

DRAWN BY: Emine Bushra Boztepe

PREPARED BY:

Carnow, Conibear & Assoc., Ltd.
Environmental Consulting Services
300 W. Adams St., Suite 1200, Chicago, IL 60606
t: 312.782.4486 f: 312.782.5145
www.ccaatd.com



CCA PROJECT NUMBER
A13367-0096

REINSPECTION DATE
DECEMBER, 2015

9TH MECH.
FLOOR






Summary of Asbestos Bulk Sampling - 10th Floor






Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
1	Terrazzo	MISC	NO	10th Floor-Main Corridors, Private and Freight Elevator Lobbies.	X			Good Condition	
3	12" x 12" Black with White Specks Floor Tile	MISC	NO	10th Floor-Rooms 1003, 1003 C, 1005, 1005 C, E, F, & G, 1006, 1050 B and Storage Room 1021.		X		Physical Damage	
4	Mastic on 12" x 12" Black with White Specks Floor Tile	MISC	NO	10th Floor-Rooms 1003, 1003 C, 1005, 1005 C, E, F, & G, 1006, 1050 B and Storage Room 1021.		X		Good Condition	
13	Carpet Mastic	MISC	YES	10th Floor-Rooms 1001 B, 1003 A, C, & E and 1005B, D, H, I & J.			X	N/A	
18	1' x 1' Spline Ceiling Tile	MISC	YES	10th Floor-Throughout Floor			X	N/A	
24	Plaster	SURF	YES	10th Floor-Throughout Floor			X	N/A	
33	Spray-On (Cementitious)	MISC	YES	10th Floor-On I-Beams Above the Drop Ceiling Throughout Floor, Including Electrical Closets.		X		Slight Damage - Debris	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.
40	Canvas Flex Duct	MISC	NO	10th Floor-Inside Perimeter Unit Vents.			X	N/A	
41	Red Sealant on Canvas Flex Duct	MISC	NO	10th Floor-Inside Perimeter Unit Vents.		X		Good Condition	
42	Grey Cementitious Board	MISC	NO	10th Floor-Room 1050 B.		X		Not Observed	Repair or Remove. Label as ACM
43	Electrical Floor Board	SURF	YES	10th Floor-Electrical Closets.		X		Slight Damage	Repair or Remove. Label as ACM
44	Pink Fire Stop	MISC	NO	10th Floor-Electrical Closets.			X	N/A	
48	Sink Undercoating (Black)	MISC	NO	10th Floor-Storage Room 1021.			X	N/A	
53	Window Glaze	MISC	NO	10th Floor-Around the Inside Perimeter of the Large Windows.			X	N/A	

Summary of Asbestos Bulk Sampling - 10th Floor


Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
54	Window Frame Caulk	MISC	NO	10th Floor-Around the Outside Perimeter of the Large Windows.	X			Good Condition	
55	Small Window Glaze	MISC	NO	10th Floor- Stairwell # 3.		X		Good Condition	
57	Red Caulk	MISC	YES	10th Floor-Electrical Closets.			X	N/A	
58	Black Sealant	MISC	NO	10th Floor-Electrical Closets.			X	N/A	
76	Fitting on Fiberglass Pipe Insulation	MISC	NO	10th Floor-Pipe and Duct Chases and Above Drop Ceilings Throughout Floor.		X		Good Condition	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.

Bold Indicates Asbestos and Assumed Asbestos Containing Materials.

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	1 Terrazzo	X		Good Condition
	3 12" x 12" Black with White Specks Floor Tile		X	Physical Damage
	4 Mastic on 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	33 Spray-On (Cementitious)		X	Slight Damage-Debris
	41 Red Sealant on Canvas Duct		X	Good Condition

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	42 Grey Cementitious Board		X	Not Observed
	43 Electrical Floor Board		X	Slight Damage
	54 Window Frame Caulk	X		Good Condition
	55 Small Window Glaze		X	Good Condition
	76 Fitting on Fiberglass Pipe Insulation		X	Good Condition

*Asbestos containing spray applied fire proofing and thermal insulation are present above existing ceiling (Exact locations not shown on drawing)



*Locations of materials updated for this 2015 Reinspection

*Entry into interstitial space above existing ceiling requires 16 hour asbestos training, personal protective equipment and compliance with Building's asbestos operation and maintenance plan

LEGEND:
Material Symbol LOCATIONS OF ASBESTOS CONTAINING MATERIAL

PROJECT NAME:

RICHARD J. DALEY CENTER
50 W. WASHINGTON STREET
CHICAGO, ILLINOIS 60602

PREPARED FOR:

50 W. WASHINGTON STREET
SUITE 1203
CHICAGO, ILLINOIS 60602

SHEET NAME:
2015 ASBESTOS REINSPECTION - 10TH FLOOR
INSPECTED BY: James Lehnhardt
IDPH LICENSE #: 100-04208
DRAWN BY: Emine Bushra Boztepe

PREPARED BY:
Carnow, Conibear & Assoc., Ltd.
Environmental Consulting Services
300 W. Adams St., Suite 1200, Chicago, IL 60606
t: 312.782.4486 f: 312.782.5145
www.ccailld.com



CCA PROJECT NUMBER
A13367-0096
REINSPECTION DATE
DECEMBER, 2015
10TH FLOOR







Summary of Asbestos Bulk Sampling - 11th Floor






Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
1	Terrazzo	MISC	NO	11th Floor-Main Corridors, Private and Freight Elevator Lobbies.	X			Good Condition	
3	12" x 12" Black with White Specks Floor Tile	MISC	YES	11th Floor-Room 1150 B.		X		Partially Abated	
4	Mastic on 12" x 12" Black with White Specks Floor Tile	MISC	NO	11th Floor-Room 1150 B.		X		Good Condition	
14	Carpet Mastic w/ Black Mastic Underneath	MISC	NO	11th Floor-Throughout Hallways, Courtrooms and Judges Chambers.		X		Good Condition	Partial Abatement in July 2012 and Spring 2014
18	1' x 1' Spline Ceiling Tile	MISC	YES	11th Floor-Throughout Floor.			X	N/A	
24	Plaster	SURF	YES	11th Floor-Throughout Floor.			X	N/A	
33	Spray-On (Cementitious)	MISC	NO	11th Floor-On I-Beams Above the Drop Ceiling Throughout Floor, Including Electrical Closets.		X		Slight Damage - Debris	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.
40	Canvas Flex Duct	MISC	NO	11th Floor-Inside Perimeter Unit Vents.			X	N/A	
41	Red Sealant on Canvas Flex Duct	MISC	NO	11th Floor-Inside Perimeter Unit Vents.		X		Good Condition	
42	Grey Cementitious Board	MISC	NO	11th Floor-Room 1150 B.		X		Abated	Repair or Remove. Label as ACM
43	Electrical Floor Board	MISC	YES	11th Floor-Electrical Closets.		X		Slight Damage	Repair or Remove. Label as ACM
44	Pink Fire Stop	SURF	YES	11th Floor-Electrical Closets.			X	N/A	
45	White Fire Stop	MISC	NO	11th Floor-Electrical Closet A.			X	N/A	
48	Electrical Tape (Black)	MISC	YES	11th Floor-Telephone Closet.			X	N/A	
53	Window Glaze	MISC	NO	11th Floor-Around the Inside Perimeter of the Large Windows.			X	N/A	

Summary of Asbestos Bulk Sampling - 11th Floor


Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
54	Window Frame Caulk	MISC	NO	11th Floor-Around the Outside Perimeter of the Large Windows.	X			Good Condition	
55	Small Window Glaze	MISC	NO	11th Floor-Stairwell # 3.		X		Good Condition	
57	Red Caulk	MISC	NO	11th Floor-Electrical and Telephone Closets.			X	N/A	
58	Black Sealant	MISC	NO	11th Floor-Electrical and Telephone Closets.			X	N/A	
76	Fittings on Fiberglass Pipe Insulation	MISC	NO	11th Floor-Pipe Chases and above Drop Ceilings Throughout Floor.	X			Good Condition	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.

Bold Indicates Asbestos and Assumed Asbestos Containing Materials.

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	1 Terrazzo	X		Good Condition
	3 12" x 12" Black with White Specks Floor Tile		X	Partially Abated
	4 Mastic on 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	14 Carpet Mastic with Black Mastic underneath		X	Good Condition
	33 Spray-On (Cementitious)		X	Slight Damage-Debris
	41 Red Sealant on Canvas Duct		X	Good Condition

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	42 Grey Cementitious Board		X	Abated
	43 Electrical Floor Board		X	Slight Damage
	54 Window Frame Caulk	X		Good Condition
	55 Small Window Glaze		X	Good Condition
	76 Fitting on Fiberglass Pipe Insulation	X		Good Condition

*Asbestos containing spray applied fire proofing and thermal insulation are present above existing ceiling (Exact locations not shown on drawing)



*Locations of materials updated for this 2015 Reinspection

*Entry into interstitial space above existing ceiling requires 16 hour asbestos training, personal protective equipment and compliance with Building's asbestos operation and maintenance plan

LEGEND:
Material Symbol LOCATIONS OF ASBESTOS CONTAINING MATERIAL

PROJECT NAME:

RICHARD J. DALEY CENTER
50 W. WASHINGTON STREET
CHICAGO, ILLINOIS 60602

PREPARED FOR:

50 W. WASHINGTON STREET
SUITE 1203
CHICAGO, ILLINOIS 60602

SHEET NAME:
2015 ASBESTOS REINSPECTION - 11TH FLOOR
INSPECTED BY: James Lehnhardt
IDPH LICENSE #: 100-04208
DRAWN BY: Emine Bushra Boztepe

PREPARED BY:
Carnow, Conibear & Assoc., Ltd.
Environmental Consulting Services
300 W. Adams St., Suite 1200, Chicago, IL 60606
t: 312.782.4486 f: 312.782.5145
www.ccailld.com



CCA PROJECT NUMBER
A13367-0096
REINSPECTION DATE
DECEMBER, 2015
11TH FLOOR






Summary of Asbestos Bulk Sampling - 12th Floor






Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
1	Terrazzo	MISC	NO	12th Floor-Main Corridors, Private and Freight Elevator Lobbies.	X			Good Condition	
3	12" x 12" Black with White Specks Floor Tile	MISC	NO	12th Floor-Rooms 1201, 1202 and 1250 Janitor's Closet.		X		Good Condition	
4	Mastic on 12" x 12" Black with White Specks Floor Tile	MISC	NO	12th Floor-Rooms 1201, 1202 and 1250 Janitor's Closet.		X		Good Condition	
13	Carpet Mastic	MISC	NO	12th Floor-Room 1203.			X	N/A	
16	4" Black Vinyl Baseboard	MISC	NO	12th Floor-Room 1250 Janitor's Closet.			X	N/A	
17	Adhesive on 4" Black Vinyl Baseboard	MISC	NO	12th Floor-Room 1250 Janitor's Closet.			X	N/A	
18	1' x 1' Spline Ceiling Tile	MISC	YES	12th Floor-Throughout Floor.			X	N/A	
24	Plaster	SURF	YES	12th Floor-Throughout Floor.			X	N/A	
27	Drywall Joint/Compound	MISC	NO	12th Floor-Various Areas.			X	N/A	
33	Spray-On (Cementitious)	MISC	NO	12th Floor-On I-Beams Above Drop Ceilings Throughout Floor, Including Electrical Closets.		X		Slight Damage	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.
40	Canvas Flex Duct	MISC	NO	12th Floor-Inside Perimeter Unit Vents.			X	N/A	
41	Red Sealant on Canvas Flex Duct	MISC	NO	12th Floor-Inside Perimeter Unit Vents.		X		Good Condition	
42	Grey Cementitious Board	MISC	NO	12th Floor-Room 1250 B.		X		Not Observed	Repair or Remove. Label as ACM
43	Electrical Floor Board	MISC	YES	12th Floor-Electrical Closets.		X		Slight Damage	Repair or Remove. Label as ACM
44	Pink Fire Stop	MISC	NO	12th Floor-Electrical Closets.			X	N/A	
45	White Fire Stop	MISC	YES	12th Floor-Electrical Closet A.			X	N/A	
48	Sink Undercoating (White)	MISC	NO	12th Floor-Room 1203 E.			X	N/A	

Summary of Asbestos Bulk Sampling - 12th Floor


Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
53	Window Glaze	MISC	NO	12th Floor-Around the inside Perimeter of the Large Windows.			X	N/A	
54	Window Frame Caulk	MISC	NO	12th Floor-Around the Outside Perimeter of the Large Windows.	X			Good Condition	
55	Small Window Glaze	MISC	NO	12th Floor-Stairwell # 3.		X		Good Condition	
57	Red Caulk	SURF	YES	12th Floor-Electrical and Telephone Closets.			X	N/A	
58	Black Sealant	MISC	NO	12th Floor-Electrical and Telephone Closets.			X	N/A	
76	Fittngs on Fiberglass Pipe Insulation	MISC	NO	12th Floor-Pipe Chases and Above Drop Ceilings Throughout Floor.	X			Good Condition	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.

Bold Indicates Asbestos and Assumed Asbestos Containing Materials.

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	1 Terrazzo	X		Good Condition
	3 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	4 Mastic on 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	33 Spray-On (Cementitious)		X	Slight Damage
	41 Red Sealant on Canvas Duct		X	Good Condition

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	42 Grey Cementitious Board		X	Not Observed
	43 Electrical Floor Board		X	Slight Damage
	54 Window Frame Caulk	X		Good Condition
	55 Small Window Glaze		X	Good Condition
	76 Fitting on Fiberglass Pipe Insulation	X		Good Condition

*Asbestos containing spray applied fire proofing and thermal insulation are present above existing ceiling (Exact locations not shown on drawing)



*Locations of materials updated for this 2015 Reinspection

*Entry into interstitial space above existing ceiling requires 16 hour asbestos training, personal protective equipment and compliance with Building's asbestos operation and maintenance plan

LEGEND:

 LOCATIONS OF ASBESTOS CONTAINING MATERIAL

PROJECT NAME:



RICHARD J. DALEY CENTER

50 W. WASHINGTON STREET
CHICAGO, ILLINOIS 60602

PREPARED FOR:



50 W. WASHINGTON STREET
SUITE 1203
CHICAGO, ILLINOIS 60602

SHEET NAME:

2015 ASBESTOS REINSPECTION - 12TH FLOOR

INSPECTED BY: James Lehnhardt

IDPH LICENSE #: 100-04208

DRAWN BY: Emine Bushra Boztepe

PREPARED BY:

Carnow, Conibear & Assoc., Ltd.
Environmental Consulting Services
300 W. Adams St., Suite 1200, Chicago, IL 60606
t: 312.782.4486 f: 312.782.5145
www.ccalltd.com



CCA PROJECT NUMBER
A13367-0096

REINSPECTION DATE
DECEMBER, 2015

12TH FLOOR

Summary of Asbestos Bulk Sampling - 13th Floor

Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
1	Terrazzo	MISC	NO	13th Floor-Main Corridors, Private and Freight Elevator Lobbies.	X			Good Condition	
3	12" x 12" Black with White Specks Floor Tile	MISC	NO	13th Floor-Room 1300 A.		X		Good Condition	
4	Mastic on 12" x 12" Black with White Specks Floor Tile	MISC	NO	13th Floor-Room 1300 A.		X		Good Condition	
13	Carpet Mastic	MISC	NO	13th Floor-Throughout Courtrooms and Office Areas.			X	N/A	
16	Adhesive on 4" Black Vinyl Baseboard	MISC	NO	13th Floor-Room Janitor's Closet.			X	N/A	
18	1' x 1' Spline Ceiling Tile	MISC	YES	13th Floor-Throughout Floor.			X	N/A	
24	Plaster	SURF	YES	13th Floor-Throughout Floor.			X	N/A	
33	Spray-On (Cementitious)	MISC	NO	13th Floor-On I-Beams Above Drop Ceilings Throughout Floor, Including Electrical Closets.		X		Slight Damage - Debris	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.
40	Canvas Flex Duct	MISC	NO	13th Floor-Inside Perimeter Unit Vents.			X	N/A	
41	Red Sealant on Canvas Flex Duct	MISC	NO	13th Floor-Inside Perimeter Unit Vents.		X		Good Condition	
42	Grey Cementitious Board	MISC	NO	13th Floor-Room 1300 B.		X		Not Observed	Repair or Remove. Label as ACM
43	Electrical Floor Board	MISC	YES	13th Floor-Electrical Closets.		X		Slight Damage	Repair or Remove. Label as ACM
44	Pink Fire Stop	MISC	NO	13th Floor-Electrical Closets.			X	N/A	
53	Window Glaze	MISC	NO	13th Floor-Around the inside Perimeter of the Large Windows.			X	N/A	
54	Window Frame Caulk	MISC	NO	13th Floor-Around the Outside Perimeter of the Large Windows.		X		Good Condition	
55	Small Window Glaze	MISC	NO	13th Floor-Stairwell # 3.		X		Good Condition	

Summary of Asbestos Bulk Sampling - 13th Floor


Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
57	Red Caulk	SURF	YES	13th Floor-Electrical and Telephone Closets.			X	N/A	
58	Black Sealant	MISC	NO	13th Floor-Electrical and Telephone Closets.			X	N/A	
76	Fittings on Fiberglass Pipe Insulation	MISC	NO	13th Floor-Pipe Chases and Above Drop Ceilings Throughout Floor.	X			Good Condition	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.

Bold Indicates Asbestos and Assumed Asbestos Containing Materials.

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	1 Terrazzo	X		Good Condition
	3 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	4 Mastic on 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	33 Spray-On (Cementitious)		X	Slight Damage-Debris
	41 Red Sealant on Canvas Duct		X	Good Condition

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	42 Grey Cementitious Board		X	Not Observed
	43 Electrical Floor Board		X	Slight Damage
	54 Window Frame Caulk		X	Good Condition
	55 Small Window Glaze		X	Good Condition
	76 Fitting on Fiberglass Pipe Insulation	X		Good Condition

*Asbestos containing spray applied fire proofing and thermal insulation are present above existing ceiling (Exact locations not shown on drawing)



*Locations of materials updated for this 2015 Reinspection

*Entry into interstitial space above existing ceiling requires 16 hour asbestos training, personal protective equipment and compliance with Building's asbestos operation and maintenance plan

LEGEND:
Material Symbol LOCATIONS OF ASBESTOS CONTAINING MATERIAL

PROJECT NAME:

RICHARD J. DALEY CENTER
50 W. WASHINGTON STREET
CHICAGO, ILLINOIS 60602

PREPARED FOR:

50 W. WASHINGTON STREET
SUITE 1203
CHICAGO, ILLINOIS 60602

SHEET NAME:
2015 ASBESTOS REINSPECTION - 13TH FLOOR
INSPECTED BY: James Lehnhardt
IDPH LICENSE #: 100-04208
DRAWN BY: Emine Bushra Boztepe

PREPARED BY:
Carnow, Conibear & Assoc., Ltd.
Environmental Consulting Services
300 W. Adams St., Suite 1200, Chicago, IL 60606
t: 312.782.4486 f: 312.782.5145
www.ccailld.com



CCA PROJECT NUMBER
A13367-0096
REINSPECTION DATE
DECEMBER, 2015
13TH FLOOR






Summary of Asbestos Bulk Sampling - 14th Floor






Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
1	Terrazzo	MISC	NO	14th Floor-Main Corridors, Private and Freight Elevator Lobbies.	X			Good Condition	
3	12" x 12" Black with White Specks Floor Tile	MISC	NO	14th Floor.		X		Good Condition	
4	Mastic on 12" x 12" Black with White Specks Floor Tile	MISC	NO	14th Floor.		X		Good Condition	
13	Carpet Mastic	MISC	NO	14th Floor-Throughout Courtrooms and Office Areas.			X	N/A	
16	Adhesive on 4" Black Vinyl Baseboard	MISC	NO	14th Floor.			X	N/A	
18	1' x 1' Spline Ceiling Tile	MISC	YES	14th Floor-Throughout Floor.			X	N/A	
24	Plaster	SURF	YES	14th Floor-Throughout Floor.			X	N/A	
33	Spray-On (Cementitious)	MISC	NO	14th Floor-On I-Beams Above Drop Ceilings Throughout Floor, Including Electrical Closets.		X		Slight Damage - Debris	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.
40	Canvas Flex Duct	MISC	NO	14th Floor-Inside Perimeter Unit Vents.			X	N/A	
41	Red Sealant on Canvas Flex Duct	MISC	NO	14th Floor-Inside Perimeter Unit Vents.		X		Good Condition	
42	Grey Cementitious Board	MISC	NO	14th Floor-Room 1400 A.		X		Not Observed	Repair or Remove. Label as ACM
43	Electrical Floor Board	MISC	YES	14th Floor-Electrical Closets.		X		Slight Damage - Debris	Repair or Remove. Label as ACM
44	Pink Fire Stop	MISC	NO	14th Floor-Electrical Closets.			X	N/A	
45	White Fire Stop	MISC	NO	14th Floor-Electrical Closets.			X	N/A	
47	Electrical Tape	MISC	NO	14th Floor-Telephone Room.			X	N/A	
53	Window Glaze	MISC	NO	14th Floor-Around the inside Perimeter of the Large Windows.			X	N/A	

Summary of Asbestos Bulk Sampling - 14th Floor

Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
54	Window Frame Caulk	MISC	NO	14th Floor-Around the Outside Perimeter of the Large Windows.		X		Good Condition	
55	Small Window Glaze	MISC	NO	14th Floor-Stairwell # 3.		X		Good Condition	
57	Red Caulk	SURF	YES	14th Floor-Electrical and Telephone Closets.			X	N/A	
58	Black Sealant	MISC	NO	14th Floor-Electrical and Telephone Closets.			X	N/A	
60	Grey Wall Sealant	MISC	NO	14th Floor-Electrical Closets.			X	N/A	
76	Fittings on Fiberglass Pipe Insulation	MISC	NO	14th Floor-Pipe Chases and Above Drop Ceilings Throughout Floor.	X			Good Condition	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.

Bold Indicates Asbestos and Assumed Asbestos Containing Materials.

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	1 Terrazzo	X		Good Condition
	3 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	4 Mastic on 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	33 Spray-On (Cementitious)		X	Slight Damage-Debris
	41 Red Sealant on Canvas Duct		X	Good Condition

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	42 Grey Cementitious Board		X	Not Observed
	43 Electrical Floor Board		X	Slight Damage
	54 Window Frame Caulk		X	Good Condition
	55 Small Window Glaze		X	Good Condition
	76 Fitting on Fiberglass Pipe Insulation	X		Good Condition

*Asbestos containing spray applied fire proofing and thermal insulation are present above existing ceiling (Exact locations not shown on drawing)



*Locations of materials updated for this 2015 Reinspection

*Entry into interstitial space above existing ceiling requires 16 hour asbestos training, personal protective equipment and compliance with Building's asbestos operation and maintenance plan

LEGEND:
Material Symbol LOCATIONS OF ASBESTOS CONTAINING MATERIAL

PROJECT NAME:

RICHARD J. DALEY CENTER
50 W. WASHINGTON STREET
CHICAGO, ILLINOIS 60602

PREPARED FOR:

50 W. WASHINGTON STREET
SUITE 1203
CHICAGO, ILLINOIS 60602

SHEET NAME:
2015 ASBESTOS REINSPECTION - 14TH FLOOR
INSPECTED BY: James Lehnhardt
IDPH LICENSE #: 100-04208
DRAWN BY: Emine Bushra Boztepe

PREPARED BY:
Carnow, Conibear & Assoc., Ltd.
Environmental Consulting Services
300 W. Adams St., Suite 1200, Chicago, IL 60606
t: 312.782.4486 f: 312.782.5145
www.ccailld.com



CCA PROJECT NUMBER
A13367-0096
REINSPECTION DATE
DECEMBER, 2015
14TH FLOOR

Summary of Asbestos Bulk Sampling - 15th Floor

Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
1	Terrazzo	MISC	NO	15th Floor-Main Corridors, Private and Freight Elevator Lobbies.	X			Good Condition	
13	Carpet Mastic	MISC	NO	15th Floor-Throughout Courtrooms and Office Areas.			X	N/A	
18	1' x 1' Spline Ceiling Tile	MISC	YES	15th Floor-Throughout Floor.			X	N/A	
24	Plaster	SURF	YES	15th Floor-Throughout Floor.			X	N/A	
33	Spray-On (Cementitious)	MISC	NO	15th Floor-On I-Beams Above Drop Ceilings Throughout Floor, Including Electrical Closets.		X		Slight Damage - Debris	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.
40	Canvas Flex Duct	MISC	NO	15th Floor-Inside Perimeter Unit Vents.			X	N/A	
41	Red Sealant on Canvas Flex Duct	MISC	NO	15th Floor-Inside Perimeter Unit Vents.		X		Good Condition	
42	Grey Cementitious Board	MISC	NO	15th Floor-Room 1400 A.		X		Not Observed	Repair or Remove. Label as ACM
43	Electrical Floor Board	MISC	YES	15th Floor-Electrical Closets.		X		Slight Damage - Debris	Repair or Remove. Label as ACM
44	Pink Fire Stop	MISC	NO	15th Floor-Electrical Closets.			X	N/A	
47	Electrical Tape	MISC	NO	15th Floor-Telephone Room.			X	N/A	
53	Window Glaze	MISC	NO	15th Floor-Around the inside Perimeter of the Large Windows.			X	N/A	Material sampled 2015
54	Window Frame Caulk	MISC	NO	15th Floor-Around the Outside Perimeter of the Large Windows.		X		Good Condition	
55	Small Window Glaze	MISC	NO	15th Floor-Stairwell # 3.		X		Good Condition	
57	Red Caulk	SURF	YES	15th Floor-Electrical and Telephone Closets.			X	N/A	
58	Black Sealant	MISC	NO	15th Floor-Electrical and Telephone Closets.			X	N/A	

Summary of Asbestos Bulk Sampling - 15th Floor


Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
76	Fittngs on Fiberglass Pipe Insulation	MISC	NO	15th Floor-Pipe Chases and Above Drop Ceilings Throughout Floor.	X			Good Condition	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.

Bold Indicates Asbestos and Assumed Asbestos Containing Materials.

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	1 Terrazzo	X		Good Condition
	33 Spray-On (Cementitious)		X	Slight Damage-Debris
	41 Red Sealant on Canvas Duct		X	Good Condition
	42 Grey Cementitious Board		X	Not Observed
	43 Electrical Floor Board		X	Slight Damage

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	54 Window Frame Caulk		X	Good Condition
	55 Small Window Glaze		X	Good Condition
	76 Fitting on Fiberglass Pipe Insulation	X		Good Condition

*Asbestos containing spray applied fire proofing and thermal insulation are present above existing ceiling (Exact locations not shown on drawing)



*Locations of materials updated for this 2015 Reinspection

*Entry into interstitial space above existing ceiling requires 16 hour asbestos training, personal protective equipment and compliance with Building's asbestos operation and maintenance plan

LEGEND:
Material Symbol LOCATIONS OF ASBESTOS CONTAINING MATERIAL

PROJECT NAME:

RICHARD J. DALEY CENTER
50 W. WASHINGTON STREET
CHICAGO, ILLINOIS 60602

PREPARED FOR:

50 W. WASHINGTON STREET
SUITE 1203
CHICAGO, ILLINOIS 60602

SHEET NAME:
2015 ASBESTOS REINSPECTION - 15TH FLOOR
INSPECTED BY: James Lehnhardt
IDPH LICENSE #: 100-04208
DRAWN BY: Emine Bushra Boztepe

PREPARED BY:
Carnow, Conibear & Assoc., Ltd.
Environmental Consulting Services
300 W. Adams St., Suite 1200, Chicago, IL 60606
t: 312.782.4486 f: 312.782.5145
www.ccailld.com



CCA PROJECT NUMBER
A13367-0096
REINSPECTION DATE
DECEMBER, 2015
15TH FLOOR






Summary of Asbestos Bulk Sampling - 16th Floor






Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
1	Terrazzo	MISC	NO	16th Floor-Main Corridors, Private and Freight Elevator Lobbies.	X			Good Condition	
3	12" x 12" Black with White Specks Floor Tile	MISC	NO	16th Floor-Storage Room 1603.		X		Good Condition	
4	Mastic on 12" x 12" Black with White Specks Floor Tile	MISC	NO	16th Floor-Storage Room 1603.		X		Good Condition	
13	Carpet Mastic	MISC	NO	16th Floor-Throughout Courtrooms and Office Areas.			X	N/A	
16	Adhesive on 4" Vinyl Baseboard	MISC	NO	16th Floor-Janitor's Closet.			X	N/A	
18	1' x 1' Spline Ceiling Tile	MISC	YES	16th Floor-Throughout Floor.			X	N/A	
24	Plaster	SURF	YES	16th Floor-Throughout Floor.			X	N/A	
33	Spray-On (Cementitious)	MISC	NO	16th Floor-On I-Beams Above Drop Ceilings Throughout Floor, Including Electrical Closets.		X		Slight Damage - Debris	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.
40	Canvas Flex Duct	MISC	NO	16th Floor-Inside Perimeter Unit Vents.			X	N/A	
41	Red Sealant on Canvas Flex Duct	MISC	NO	16th Floor-Inside Perimeter Unit Vents.		X		Good Condition	
42	Grey Cementitious Board	MISC	NO	16th Floor-Room 1400 A.		X		Not Observed	Repair or Remove. Label as ACM
43	Electrical Floor Board	MISC	YES	16th Floor-Electrical Closets.		X		Slight Damage	Repair or Remove. Label as ACM
44	Pink Fire Stop	MISC	NO	16th Floor-Electrical Closets.			X	N/A	
53	Window Glaze	MISC	NO	16th Floor-Around the inside Perimeter of the Large Windows.			X	N/A	
54	Window Frame Caulk	MISC	NO	16th Floor-Around the Outside Perimeter of the Large Windows.		X		Good Condition	
55	Small Window Glaze	MISC	NO	16th Floor-Stairwell # 3.	X			Good Condition	

Summary of Asbestos Bulk Sampling - 16th Floor


Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
57	Red Caulk	SURF	YES	16th Floor-Electrical and Telephone Closets.			X	N/A	
58	Black Sealant	MISC	NO	16th Floor-Electrical and Telephone Closets.			X	N/A	
76	Fittings on Fiberglass Pipe Insulation	MISC	NO	16th Floor-Pipe Chases and Above Drop Ceilings Throughout Floor.	X			Good Condition	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.

Bold Indicates Asbestos and Assumed Asbestos Containing Materials.

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	1 Terrazzo	X		Good Condition
	3 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	4 Mastic on 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	33 Spray-On (Cementitious)		X	Slight Damage-Debris
	41 Red Sealant on Canvas Duct		X	Good Condition

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	42 Grey Cementitious Board		X	Not Observed
	43 Electrical Floor Board		X	Slight Damage
	54 Window Frame Caulk		X	Good Condition
	55 Small Window Glaze	X		Good Condition
	76 Fitting on Fiberglass Pipe Insulation	X		Good Condition

*Asbestos containing spray applied fire proofing and thermal insulation are present above existing ceiling (Exact locations not shown on drawing)



*Locations of materials updated for this 2015 Reinspection

*Entry into interstitial space above existing ceiling requires 16 hour asbestos training, personal protective equipment and compliance with Building's asbestos operation and maintenance plan

LEGEND:
Material Symbol LOCATIONS OF ASBESTOS CONTAINING MATERIAL

PROJECT NAME:

RICHARD J. DALEY CENTER
50 W. WASHINGTON STREET
CHICAGO, ILLINOIS 60602

PREPARED FOR:

50 W. WASHINGTON STREET
SUITE 1203
CHICAGO, ILLINOIS 60602

SHEET NAME:
2015 ASBESTOS REINSPECTION - 16TH FLOOR
INSPECTED BY: James Lehnhardt
IDPH LICENSE #: 100-04208
DRAWN BY: Emine Bushra Boztepe

PREPARED BY:
Carnow, Conibear & Assoc., Ltd.
Environmental Consulting Services
300 W. Adams St., Suite 1200, Chicago, IL 60606
t: 312.782.4486 f: 312.782.5145
www.ccailld.com



CCA PROJECT NUMBER
A13367-0096
REINSPECTION DATE
DECEMBER, 2015

16TH FLOOR







Summary of Asbestos Bulk Sampling - 17th Floor







Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
1	Terrazzo	MISC	NO	17th Floor-Main Corridors, Private and Freight Elevator Lobbies.	X			Good Condition	
3	12" x 12" Black with White Specks Floor Tile	MISC	NO	17th Floor-Storage Room 1703.		X		Good Condition	
4	Mastic on 12" x 12" Black with White Specks Floor Tile	MISC	NO	17th Floor-Storage Room 1703.		X		Good Condition	
13	Carpet Mastic	MISC	NO	17th Floor-Throughout Courtrooms and Office Areas.			X	N/A	
16	Adhesive on 4" Black Vinyl Baseboard	MISC	NO	17th Floor-Janitor's Closet.			X	N/A	
18	1' x 1' Spline Ceiling Tile	MISC	YES	17th Floor-Throughout Floor.			X	N/A	
24	Plaster	SURF	YES	17th Floor-Throughout Floor.			X	N/A	
33	Spray-On (Cementitious)	MISC	NO	17th Floor-On I-Beams Above Drop Ceilings Throughout Floor, Including Electrical Closets.		X		Slight Damage - Debris	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.
40	Canvas Flex Duct	MISC	NO	17th Floor-Inside Perimeter Unit Vents.			X	N/A	
41	Red Sealant on Canvas Flex Duct	MISC	NO	17th Floor-Inside Perimeter Unit Vents.		X		Good Condition	
42	Grey Cementitious Board	MISC	NO	17th Floor-Room 1400 A.		X		Abated	Repair or Remove. Label as ACM
43	Electrical Floor Board	MISC	YES	17th Floor-Electrical Closets.		X		Not Observed	Repair or Remove. Label as ACM
44	Pink Fire Stop	MISC	NO	17th Floor-Electrical Closets.			X	N/A	
53	Window Glaze	MISC	NO	17th Floor-Around the inside Perimeter of the Large Windows.		X		Good Condition	
54	Window Frame Caulk	MISC	NO	17th Floor-Around the Outside Perimeter of the Large Windows.		X		Good Condition	

Summary of Asbestos Bulk Sampling - 17th Floor


Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
55	Small Window Glaze	MISC	NO	17th Floor-Stairwell # 3.		X		Good Condition	
57	Red Caulk	SURF	YES	17th Floor-Electrical and Telephone Closets.			X	N/A	
58	Black Sealant	MISC	NO	17th Floor-Electrical and Telephone Closets.			X	N/A	
76	Fittings on Fiberglass Pipe Insulation	MISC	NO	17th Floor-Pipe Chases and Above Drop Ceilings Throughout Floor.	X			Good Condition	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.
144	Plaster with Over-Spray from HA 33	MISC	NO	17th Floor-Throughout Floor.	X			Good Condition	

Bold Indicates Asbestos and Assumed Asbestos Containing Materials.

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	1 Terrazzo	X		Good Condition
	3 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	4 Mastic on 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	33 Spray-On (Cementitious)		X	Slight Damage-Debris
	41 Red Sealant on Canvas Duct		X	Good Condition
	42 Grey Cementitious Board		X	Abated

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	43 Electrical Floor Board		X	Not Observed
	53 Window Glaze		X	Good Condition
	54 Window Frame Caulk		X	Good Condition
	55 Small Window Glaze		X	Good Condition
	76 Fitting on Fiberglass Pipe Insulation	X		Good Condition
	144 Plaster with Over-Spray from HA-33	X		Good Condition

*Asbestos containing spray applied fire proofing and thermal insulation are present above existing ceiling (Exact locations not shown on drawing)



*Locations of materials updated for this 2015 Reinspection

*Entry into interstitial space above existing ceiling requires 16 hour asbestos training, personal protective equipment and compliance with Building's asbestos operation and maintenance plan

LEGEND:
Material Symbol LOCATIONS OF ASBESTOS CONTAINING MATERIAL

PROJECT NAME:

RICHARD J. DALEY CENTER
50 W. WASHINGTON STREET
CHICAGO, ILLINOIS 60602

PREPARED FOR:

50 W. WASHINGTON STREET
SUITE 1203
CHICAGO, ILLINOIS 60602

SHEET NAME:
2015 ASBESTOS REINSPECTION - 17TH FLOOR
INSPECTED BY: James Lehnhardt
IDPH LICENSE #: 100-04208
DRAWN BY: Emine Bushra Boztepe

PREPARED BY:
Carnow, Conibear & Assoc., Ltd.
Environmental Consulting Services
300 W. Adams St., Suite 1200, Chicago, IL 60606
t: 312.782.4486 f: 312.782.5145
www.ccailld.com



CCA PROJECT NUMBER
A13367-0096
REINSPECTION DATE
DECEMBER, 2015
17TH FLOOR






Summary of Asbestos Bulk Sampling - 18th Floor






Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
1	Terrazzo	MISC	NO	18th Floor-Main Corridors, Private and Freight Elevator Lobbies.	X			Good Condition	
3	12" x 12" Black with White Specks Floor Tile	MISC	NO	18th Floor-Storage Room 1803 & 1804, Telephone Closet North.		X		Good Condition	
4	Mastic on 12" x 12" Black with White Specks Floor Tile	MISC	NO	18th Floor-Storage Room 1803 & 1804, Telephone Closet North.		X		Good Condition	
13	Carpet Mastic	MISC	NO	18th Floor-Throughout Courtrooms and Office Areas.			X	N/A	
16	4" Black Vinyl Baseboard	MISC	NO	18th Floor-1806 Janitor's Closet.			X	N/A	
17	Adhesive on 4" Black Vinyl Baseboard	MISC	NO	18th Floor-1806 Janitor's Closet.			X	N/A	
18	1' x 1' Spline Ceiling Tile	MISC	YES	18th Floor-Throughout Floor.			X	N/A	
24	Plaster	SURF	YES	18th Floor-Throughout Floor.			X	N/A	
27	Drywall/Joint Compound	MISC	NO	18th Floor- Room 1800 and Telephone Closet South.			X	N/A	
33	Spray-On (Cementitious)	MISC	NO	18th Floor-On I-Beams Above Drop Ceilings Throughout Floor, Including Electrical Closets.		X		Slight Damage - Debris	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.
40	Canvas Flex Duct	MISC	NO	18th Floor-Inside Perimeter Unit Vents.			X	N/A	
41	Red Sealant on Canvas Duct	MISC	NO	18th Floor-Inside Perimeter Unit Vents.		X		Good Condition	
42	Grey Cementitious Board	MISC	NO	18th Floor-Room 1400 A.		X		Not Observed	Repair or Remove. Label as ACM
43	Electrical Floor Board	MISC	YES	18th Floor-Electrical Closets.		X		Slight Damage	Repair or Remove. Label as ACM
44	Pink Fire Stop	MISC	NO	18th Floor-Electrical Closets.			X	N/A	

Summary of Asbestos Bulk Sampling - 18th Floor


Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
49	Elevator Gasket	MISC	NO	18th Floor-E.M.R. (on elevator mechanical equipment)			X	N/A	
50	Black Filter material	MISC	NO	18th Floor-E.M.R. (on elevator mechanical equipment)			X	N/A	
51	Pyro Bar	MISC	YES	18th Floor-Electrical Closets B & C and Rooms 1813 A & B.			X	N/A	
53	Window Glaze	MISC	NO	18th Floor-Around the inside Perimeter of the Large Windows.			X	N/A	
54	Window Frame Caulk	MISC	NO	18th Floor-Around the Outside Perimeter of the Large Windows.			X	Good Condition	
55	Small Window Glaze	MISC	NO	18th Floor-Stairwell # 3.			X	Good Condition	
57	Red Caulk	SURF	YES	18th Floor-Electrical and Telephone Closets.			X	N/A	
76	Fittngs on Fiberglass Pipe Insulation	MISC	NO	18th Floor-Pipe Chases and Above Drop Ceilings Throughout Floor.	X			Good Condition	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.

Bold Indicates Asbestos and Assumed Asbestos Containing Materials.

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	1 Terrazzo	X		Good Condition
	3 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	4 Mastic on 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	33 Spray-On (Cementitious)		X	Slight Damage-Debris
	41 Red Sealant on Canvas Duct		X	Good Condition

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	42 Grey Cementitious Board		X	Not Observed
	43 Electrical Floor Board		X	Slight Damage
	54 Window Frame Caulk		X	Good Condition
	55 Small Window Glaze		X	Good Condition
	76 Fitting on Fiberglass Pipe Insulation	X		Good Condition

*Asbestos containing spray applied fire proofing and thermal insulation are present above existing ceiling (Exact locations not shown on drawing)



*Locations of materials updated for this 2015 Reinspection

*Entry into interstitial space above existing ceiling requires 16 hour asbestos training, personal protective equipment and compliance with Building's asbestos operation and maintenance plan

LEGEND:
Material Symbol LOCATIONS OF ASBESTOS CONTAINING MATERIAL

PROJECT NAME:

RICHARD J. DALEY CENTER
50 W. WASHINGTON STREET
CHICAGO, ILLINOIS 60602

PREPARED FOR:

50 W. WASHINGTON STREET
SUITE 1203
CHICAGO, ILLINOIS 60602

SHEET NAME:
2015 ASBESTOS REINSPECTION - 18TH FLOOR
INSPECTED BY: James Lehnhardt
IDPH LICENSE #: 100-04208
DRAWN BY: Emine Bushra Boztepe

PREPARED BY:
Carnow, Conibear & Assoc., Ltd.
Environmental Consulting Services
300 W. Adams St., Suite 1200, Chicago, IL 60606
t: 312.782.4486 f: 312.782.5145
www.ccailld.com



CCA PROJECT NUMBER
A13367-0096
REINSPECTION DATE
DECEMBER, 2015
18TH FLOOR

Summary of Asbestos Bulk Sampling - 19th Floor

Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
1	Terrazzo	MISC	NO	19th Floor-Main Corridors, Private and Freight Elevator Lobbies.	X			Good Condition	
3	12" x 12" Black with White Specks Floor Tile	MISC	NO	19th Floor-Room 1900 A.		X		Good Condition	
4	Mastic on 12" x 12" Black with White Specks Floor Tile	MISC	NO	19th Floor-Room 1900 A.		X		Good Condition	
13	Carpet Mastic	MISC	NO	19th Floor-Throughout Courtrooms and Office Areas.			X	N/A	
18	1' x 1' Spline Ceiling Tile	MISC	YES	19th Floor-Throughout Floor.			X	N/A	
24	Plaster	SURF	YES	19th Floor-Throughout Floor.			X	N/A	
33	Spray-On (Cementitious)	MISC	NO	19th Floor-On I-Beams Above Drop Ceilings Throughout Floor, Including Electrical Closets.		X		Slight Damage - Debris	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.
40	Canvas Flex Duct	MISC	NO	19th Floor-Inside Perimeter Unit Vents.			X	N/A	
41	Red Sealant on Canvas Flex Duct	MISC	NO	19th Floor-Inside Perimeter Unit Vents.		X		Good Condition	
42	Grey Cementitious Board	MISC	NO	19th Floor-Room 1900 A.		X		Not Observed	Repair or Remove. Label as ACM
43	Electrical Floor Board	MISC	YES	19th Floor-Electrical Closets.		X		Slight Damage - Debris	Repair or Remove. Label as ACM
44	Pink Fire Stop	MISC	NO	19th Floor-Electrical Closets.			X	N/A	
51	Pyro Bar	MISC	YES	19th Floor-Electrical Closets B & C and Rooms 1900 B and Telephone A & B.			X	N/A	
53	Window Glaze	MISC	NO	19th Floor-Around the inside Perimeter of the Large Windows.			X	N/A	

Summary of Asbestos Bulk Sampling - 19th Floor


Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
54	Window Frame Caulk	MISC	NO	19th Floor-Around the Outside Perimeter of the Large Windows.	X			Good Condition	
55	Small Window Glaze	MISC	NO	19th Floor-Stairwell # 3.		X		Good Condition	
57	Red Caulk	SURF	YES	19th Floor-Electrical and Telephone Closets.			X	N/A	
58	Black Sealant	MISC	NO	19th Floor-Telephone Closet North.			X	N/A	
60	Grey Wall Sealant	MISC	NO	19th Floor-1900 B.			X	N/A	
63	Red Duct Caulk	MISC	NO	19th Floor-Mechanical Room in Center Corridor. May also exist above ceiling on ducts.		X		Good Condition	
76	Fittings on Fiberglass Pipe Insulation	MISC	NO	19th Floor-Pipe Chases and Above Drop Ceilings Throughout Floor.	X			Good Condition	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.

Bold Indicates Asbestos and Assumed Asbestos Containing Materials.

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	1 Terrazzo	X		Good Condition
	3 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	4 Mastic on 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	33 Spray-On (Cementitious)		X	Slight Damage-Debris
	41 Red Sealant on Canvas Duct		X	Good Condition
	42 Grey Cementitious Board		X	Not Observed

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	43 Electrical Floor Board		X	Slight Damage-Debris
	54 Window Frame Caulk	X		Good Condition
	55 Small Window Glaze		X	Good Condition
	63 Red duct Caulk		X	Good Condition
	76 Fitting on Fiberglass Pipe Insulation	X		Good Condition

*Asbestos containing spray applied fire proofing and thermal insulation are present above existing ceiling (Exact locations not shown on drawing)



*Locations of materials updated for this 2015 Reinspection

*Entry into interstitial space above existing ceiling requires 16 hour asbestos training, personal protective equipment and compliance with Building's asbestos operation and maintenance plan

LEGEND:

LOCATIONS OF ASBESTOS CONTAINING MATERIAL

PROJECT NAME:



RICHARD J. DALEY CENTER
50 W. WASHINGTON STREET
CHICAGO, ILLINOIS 60602

PREPARED FOR:



50 W. WASHINGTON STREET
SUITE 1203
CHICAGO, ILLINOIS 60602

SHEET NAME:

2015 ASBESTOS REINSPECTION - 19TH FLOOR

INSPECTED BY: James Lehnhardt

IDPH LICENSE #: 100-04208

DRAWN BY: Emine Bushra Boztepe

PREPARED BY:

Carnow, Conibear & Assoc., Ltd.
Environmental Consulting Services
300 W. Adams St., Suite 1200, Chicago, IL 60606
t: 312.782.4486 f: 312.782.5145
www.ccailld.com



CCA PROJECT NUMBER
A13367-0096

REINSPECTION DATE
DECEMBER, 2015

19TH FLOOR






Summary of Asbestos Bulk Sampling - 20th Floor






Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
1	Terrazzo	MISC	NO	20th Floor-Main Corridors, Private and Freight Elevator Lobbies.	X			Good Condition	
3	12" x 12" Black with White Specks Floor Tile	MISC	NO	20th Floor-Room 2000 C.		X		Good Condition	
4	Mastic on 12" x 12" Black with White Specks Floor Tile	MISC	NO	20th Floor-Room 2000 C.		X		Good Condition	
13	Carpet Mastic	MISC	NO	20th Floor-Throughout Courtrooms and Office Areas.			X	N/A	
16	4" Black Vinyl Baseboard	MISC	NO	20th Floor-2000 Janitor's Closet.			X	N/A	
17	Adhesive on 4" Black Vinyl Baseboard	MISC	NO	20th Floor-2000 Janitor's Closet.			X	N/A	
18	1' x 1' Spline Ceiling Tile	MISC	YES	20th Floor-Throughout Floor.			X	N/A	
24	Plaster	SURF	YES	20th Floor-Throughout Floor.			X	N/A	
33	Spray-On (Cementitious)	MISC	NO	20th Floor-On I-Beams Above Drop Ceilings Throughout Floor, Including Electrical Closets.		X		Slight Damage - Debris	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.
40	Canvas Flex Duct	MISC	NO	20th Floor-Inside Perimeter Unit Vents.			X	N/A	
41	Red Sealant on Canvas Flex Duct	MISC	NO	20th Floor-Inside Perimeter Unit Vents.		X		Good Condition	
42	Grey Cementitious Board	MISC	NO	20th Floor-Room 2000 B.		X		Not Observed	Repair or Remove. Label as ACM
43	Electrical Floor Board	MISC	YES	20th Floor-Electrical Closets.		X		Slight Damage	Repair or Remove. Label as ACM
44	Pink Fire Stop	MISC	NO	20th Floor-Electrical Closets.			X	N/A	
51	Pyro Bar	MISC	YES	20th Floor-Electrical Closets B & C and Rooms 2000 B and Telephone Closet North.			X	N/A	

Summary of Asbestos Bulk Sampling - 20th Floor


Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
52	Mortar on Pyro Bar	MISC	NO	20th Floor-Electrical Closets B & C and Rooms 2000 B and Telephone Closet North.			X	N/A	
53	Window Glaze	MISC	NO	20th Floor-Around the inside Perimeter of the Large Windows.			X	N/A	
54	Window Frame Caulk	MISC	NO	20th Floor-Around the Outside Perimeter of the Large Windows.		X		Good Condition	
55	Small Window Glaze	MISC	NO	20th Floor-Stairwell # 3.		X		Good Condition	
57	Red Caulk	SURF	YES	20th Floor-Electrical and Telephone Closets.			X	N/A	
76	Fittings on Fiberglass Pipe Insulation	MISC	NO	20th Floor-Pipe Chases and Above Drop Ceilings Throughout Floor.	X			Good Condition	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.

Bold Indicates Asbestos and Assumed Asbestos Containing Materials.

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	1 Terrazzo	X		Good Condition
	3 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	4 Mastic on 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	33 Spray-On (Cementitious)		X	Slight Damage-Debris
	41 Red Sealant on Canvas Duct		X	Good Condition

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	42 Grey Cementitious Board		X	Not Observed
	43 Electrical Floor Board		X	Slight Damage
	54 Window Frame Caulk		X	Good Condition
	55 Small Window Glaze		X	Good Condition
	76 Fitting on Fiberglass Pipe Insulation	X		Good Condition

*Asbestos containing spray applied fire proofing and thermal insulation are present above existing ceiling (Exact locations not shown on drawing)



*Locations of materials updated for this 2015 Reinspection

*Entry into interstitial space above existing ceiling requires 16 hour asbestos training, personal protective equipment and compliance with Building's asbestos operation and maintenance plan

LEGEND:
Material Symbol LOCATIONS OF ASBESTOS CONTAINING MATERIAL

PROJECT NAME:

RICHARD J. DALEY CENTER
50 W. WASHINGTON STREET
CHICAGO, ILLINOIS 60602

PREPARED FOR:

50 W. WASHINGTON STREET
SUITE 1203
CHICAGO, ILLINOIS 60602

SHEET NAME:
2015 ASBESTOS REINSPECTION - 20TH FLOOR
INSPECTED BY: James Lehnhardt
IDPH LICENSE #: 100-04208
DRAWN BY: Emine Bushra Boztepe

PREPARED BY:
Carnow, Conibear & Assoc., Ltd.
Environmental Consulting Services
300 W. Adams St., Suite 1200, Chicago, IL 60606
t: 312.782.4486 f: 312.782.5145
www.ccailld.com



CCA PROJECT NUMBER
A13367-0096
REINSPECTION DATE
DECEMBER, 2015
20TH FLOOR






Summary of Asbestos Bulk Sampling - 21st Floor






Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
1	Terrazzo	MISC	NO	21st Floor-Main Corridors, Private and Freight Elevator Lobbies.	X			Good Condition	
3	12" x 12" Black with White Specks Floor Tile	MISC	NO	21st Floor-Room 2100 A.		X		Good Condition	
4	Mastic on 12" x 12" Black with White Specks Floor Tile	MISC	NO	21st Floor-Room 2100 A.		X		Good Condition	
13	Carpet Mastic	MISC	NO	21st Floor-Throughout Courtrooms and Office Areas.			X	N/A	
18	1' x 1' Spline Ceiling Tile	MISC	YES	21st Floor-Throughout Floor.			X	N/A	
24	Plaster	SURF	YES	21st Floor-Throughout Floor.			X	N/A	
33	Spray-On (Cementitious)	MISC	NO	21st Floor-On I-Beams Above Drop Ceilings Throughout Floor, Including Electrical Closets.		X		Slight Damage - Debris	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.
40	Canvas Flex Duct	MISC	NO	21st Floor-Inside Perimeter Unit Vents.			X	N/A	
41	Red Sealant on Canvas Flex Duct	MISC	NO	21st Floor-Inside Perimeter Unit Vents.		X		Good Condition	
42	Grey Cementitious Board	MISC	NO	21st Floor-Room 2100 B.		X		Not Observed	Repair or Remove. Label as ACM
43	Electrical Floor Board	MISC	YES	21st Floor-Electrical Closets.		X		Slight Damage - Debris	Repair or Remove. Label as ACM
44	Pink Fire Stop	MISC	NO	21st Floor-Electrical Closets.			X	N/A	
51	Pyro Bar	MISC	YES	21st Floor-Electrical Closets B & C and Rooms 2000 B and Telephone Closet North.			X	N/A	
52	Mortar on Pyro Bar	MISC	NO	21st Floor-Electrical Closets B & C and Rooms 2000 B and Telephone Closet North.			X	N/A	

Summary of Asbestos Bulk Sampling - 21st Floor


Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
53	Window Glaze	MISC	NO	21st Floor-Around the inside Perimeter of the Large Windows.			X	N/A	
54	Window Frame Caulk	MISC	NO	21st Floor-Around the Outside Perimeter of the Large Windows.		X		Good Condition	
55	Small Window Glaze	MISC	NO	21st Floor-Stairwell # 3.		X		Good Condition	
57	Red Caulk	SURF	YES	21st Floor-Electrical and Telephone Closets.			X	N/A	
76	Fittings on Fiberglass Pipe Insulation	MISC	NO	21stFloor-Pipe Chases and Above Drop Ceilings Throughout Floor.	X			Good Condition	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.

Bold Indicates Asbestos and Assumed Asbestos Containing Materials.

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	1 Terrazzo	X		Good Condition
	3 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	4 Mastic on 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	33 Spray-On (Cementitious)		X	Slight Damage-Debris
	41 Red Sealant on Canvas Duct		X	Good Condition

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	42 Grey Cementitious Board		X	Not Observed
	43 Electrical Floor Board		X	Slight Damage-Debris
	54 Window Frame Caulk		X	Good Condition
	55 Small Window Glaze		X	Good Condition
	76 Fitting on Fiberglass Pipe Insulation	X		Good Condition

*Asbestos containing spray applied fire proofing and thermal insulation are present above existing ceiling (Exact locations not shown on drawing)



*Locations of materials updated for this 2015 Reinspection

*Entry into interstitial space above existing ceiling requires 16 hour asbestos training, personal protective equipment and compliance with Building's asbestos operation and maintenance plan

LEGEND:  LOCATIONS OF ASBESTOS CONTAINING MATERIAL	PROJECT NAME:  RICHARD J. DALEY CENTER 50 W. WASHINGTON STREET CHICAGO, ILLINOIS 60602	PREPARED FOR:  50 W. WASHINGTON STREET SUITE 1203 CHICAGO, ILLINOIS 60602	SHEET NAME: 2015 ASBESTOS REINSPECTION - 21ST FLOOR	PREPARED BY: Carnow, Conibear & Assoc., Ltd. Environmental Consulting Services 300 W. Adams St., Suite 1200, Chicago, IL 60606 t: 312.782.4486 f: 312.782.5145 www.ccailld.com	CCA PROJECT NUMBER A13367-0096
			INSPECTED BY: James Lehnhardt IDPH LICENSE #: 100-04208 DRAWN BY: Emine Bushra Boztepe		REINSPECTION DATE DECEMBER, 2015



21ST FLOOR





Summary of Asbestos Bulk Sampling - 22nd Floor





Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
1	Terrazzo	MISC	NO	22nd Floor-Main Corridors, Private and Freight Elevator Lobbies.	X			Good Condition	
13	Carpet Mastic	MISC	NO	22nd Floor-Throughout Courtrooms and Office Areas.			X	N/A	
16	4" Black Vinyl Baseboard	MISC	NO	22nd Floor-Janitor's Closet			X	N/A	
17	Adhesive 4" Black Vinyl Baseboard	MISC	NO	22nd Floor-Janitor's Closet			X	N/A	
18	1' x 1' Spline Ceiling Tile	MISC	YES	22nd Floor-Throughout Floor.			X	N/A	
24	Plaster	SURF	YES	22nd Floor-Throughout Floor.			X	N/A	
33	Spray-On (Cementitious)	MISC	NO	22nd Floor-On I-Beams Above Drop Ceilings Throughout Floor, Including Electrical Closets.		X		Slight Damage - Debris	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.
40	Canvas Flex Duct	MISC	NO	22nd Floor-Inside Perimeter Unit Vents.			X	N/A	
41	Red Sealant on Canvas Flex Duct	MISC	NO	22nd Floor-Inside Perimeter Unit Vents.		X		Good Condition	
42	Grey Cementitious Board	MISC	NO	22nd Floor-Room 2100 B.		X		Not Observed	Repair or Remove. Label as ACM
43	Electrical Floor Board	MISC	YES	22nd Floor-Electrical Closets.		X		Slight Damage	Repair or Remove. Label as ACM
44	Pink Fire Stop	MISC	NO	22nd Floor-Electrical Closets.			X	N/A	
51	Pyro Bar	MISC	YES	22nd Floor-Electrical Closets B & C and Rooms 2000 B and Telephone Closet North.			X	N/A	
52	Mortar on Pyro Bar	MISC	NO	22nd Floor-Electrical Closets B & C and Rooms 2000 B and Telephone Closet North.			X	N/A	

Summary of Asbestos Bulk Sampling - 22nd Floor


Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
53	Window Glaze	MISC	NO	22nd Floor-Around the inside Perimeter of the Large Windows.			X	N/A	
54	Window Frame Caulk	MISC	NO	22nd Floor-Around the Outside Perimeter of the Large Windows.		X		Good Condition	
55	Small Window Glaze	MISC	NO	22nd Floor-Stairwell # 3.		X		Good Condition	
57	Red Caulk	SURF	YES	22nd Floor-Electrical and Telephone Closets.			X	N/A	
58	Black Sealant	MISC	NO	22nd Floor-Electrical and Telephone Closets.			X	N/A	
76	Fittings on Fiberglass Pipe Insulation	MISC	NO	22nd Floor-Pipe Chases and Above Drop Ceilings Throughout Floor.	X			Good Condition	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.

Bold Indicates Asbestos and Assumed Asbestos Containing Materials.

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	1 Terrazzo	X		Good Condition
	33 Spray-On (Cementitious)		X	Slight Damage-Debris
	41 Red Sealant on Canvas Duct		X	Good Condition
	42 Grey Cementitious Board		X	Not Observed

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	43 Electrical Floor Board		X	Slight Damage
	54 Window Frame Caulk		X	Good Condition
	55 Small Window Glaze		X	Good Condition
	76 Fitting on Fiberglass Pipe Insulation	X	X	Good Condition

*Asbestos containing spray applied fire proofing and thermal insulation are present above existing ceiling (Locations not shown on drawing)



*Locations of materials updated for this 2015 Reinspection

*Entry into interstitial space above existing ceiling requires 16 hour asbestos training, personal protective equipment and compliance with Building's asbestos operation and maintenance plan

LEGEND:  LOCATIONS OF ASBESTOS CONTAINING MATERIAL	PROJECT NAME:  RICHARD J. DALEY CENTER 50 W. WASHINGTON STREET CHICAGO, ILLINOIS 60602	PREPARED FOR:  MB Real Estate 50 W. WASHINGTON STREET SUITE 1203 CHICAGO, ILLINOIS 60602	SHEET NAME: 2015 ASBESTOS REINSPECTION - 22ND FLOOR	PREPARED BY: Carnow, Conibear & Assoc., Ltd. Environmental Consulting Services 300 W. Adams St., Suite 1200, Chicago, IL 60606 t: 312.782.4486 f: 312.782.5145 www.ccailld.com	CCA PROJECT NUMBER A13367-0096
			INSPECTED BY: James Lehnhardt IDPH LICENSE #: 100-04208 DRAWN BY: Emine Bushra Boztepe		REINSPECTION DATE DECEMBER, 2015






Summary of Asbestos Bulk Sampling - 23rd Floor






Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
1	Terrazzo	MISC	NO	23rd Floor-Main Corridors, Private and Freight Elevator Lobbies.	X			Good Condition	
3	12" x 12" Black with White Specks Floor Tile	MISC	NO	23rd Floor-Room 2300 A.		X		Good Condition	
4	Mastic on 12" x 12" Black with White Specks Floor Tile	MISC	NO	23rd Floor-Room 2300 A.		X		Good Condition	
13	Carpet Mastic	MISC	NO	23rd Floor-Throughout Courtrooms and Office Areas.			X	N/A	
16	4" Black Vinyl Baseboard	MISC	NO	23rd Floor-Janitor's Closet			X	N/A	
17	Adhesive 4" Black Vinyl Baseboard	MISC	NO	23rd Floor-Janitor's Closet			X	N/A	
18	1' x 1' Spline Ceiling Tile	MISC	YES	23rd Floor-Throughout Floor.			X	N/A	
24	Plaster	SURF	YES	23rd Floor-Throughout Floor.			X	N/A	
33	Spray-On (Cementitious)	MISC	NO	23rd Floor-On I-Beams Above Drop Ceilings Throughout Floor, Including Electrical Closets.		X		Good Condition	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.
40	Canvas Flex Duct	MISC	NO	23rd Floor-Inside Perimeter Unit Vents.			X	N/A	
41	Red Sealant on Canvas Flex Duct	MISC	NO	23rd Floor-Inside Perimeter Unit Vents.		X		Good Condition	
42	Grey Cementitious Board	MISC	NO	23rd Floor-Room 2300 B.		X		Not Observed	Repair or Remove. Label as ACM
43	Electrical Floor Board	MISC	YES	23rd Floor-Electrical Closets.		X		Slight Damage	Repair or Remove. Label as ACM
44	Pink Fire Stop	MISC	NO	23rd Floor-Electrical Closets.			X	N/A	
51	Pyro Bar	MISC	YES	23rd Floor-Electrical Closets B & C and Rooms 2000 B and Telephone Closet North.			X	N/A	

Summary of Asbestos Bulk Sampling - 23rd Floor


Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
52	Mortar on Pyro Bar	MISC	NO	23rd Floor-Electrical Closets B & C and Rooms 2000 B and Telephone Closet North.			X	N/A	
53	Window Glaze	MISC	NO	23rd Floor-Around the inside Perimeter of the Large Windows.			X	N/A	
54	Window Frame Caulk	MISC	NO	23rd Floor-Around the Outside Perimeter of the Large Windows.		X		Good Condition	
55	Small Window Glaze	MISC	NO	23rd Floor-Stairwell # 3.		X		Good Condition	
57	Red Caulk	SURF	YES	23rd Floor-Electrical and Telephone Closets.			X	N/A	
58	Black Sealant	MISC	NO	23rd Floor-Electrical and Telephone Closets.			X	N/A	
76	Fittings on Fiberglass Pipe Insulation	MISC	NO	23rd Floor-Pipe Chases and Above Drop Ceilings Throughout Floor.	X			Good Condition	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.

Bold Indicates Asbestos and Assumed Asbestos Containing Materials.

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	1 Terrazzo	X		Good Condition
	3 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	4 Mastic on 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	33 Spray-On (Cementitious)		X	Good Condition
	41 Red Sealant on Canvas Duct		X	Good Condition

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	42 Grey Cementitious Board		X	Not Observed
	43 Electrical Floor Board		X	Slight Damage
	54 Window Frame Caulk		X	Good Condition
	55 Small Window Glaze		X	Good Condition
	76 Fitting on Fiberglass Pipe Insulation	X		Good Condition

*Asbestos containing spray applied fire proofing and thermal insulation are present above existing ceiling (Exact locations not shown on drawing)



*Locations of materials updated for this 2015 Reinspection

*Entry into interstitial space above existing ceiling requires 16 hour asbestos training, personal protective equipment and compliance with Building's asbestos operation and maintenance plan

LEGEND:
Material Symbol LOCATIONS OF ASBESTOS CONTAINING MATERIAL

PROJECT NAME:

RICHARD J. DALEY CENTER
50 W. WASHINGTON STREET
CHICAGO, ILLINOIS 60602

PREPARED FOR:

50 W. WASHINGTON STREET
SUITE 1203
CHICAGO, ILLINOIS 60602

SHEET NAME:
2015 ASBESTOS REINSPECTION - 23RD FLOOR
INSPECTED BY: James Lehnhardt
IDPH LICENSE #: 100-04208
DRAWN BY: Emine Bushra Boztepe

PREPARED BY:
Carnow, Conibear & Assoc., Ltd.
Environmental Consulting Services
300 W. Adams St., Suite 1200, Chicago, IL 60606
t: 312.782.4486 f: 312.782.5145
www.ccailld.com



CCA PROJECT NUMBER
A13367-0096
REINSPECTION DATE
DECEMBER, 2015
23RD FLOOR






Summary of Asbestos Bulk Sampling - 24th Floor






Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
1	Terrazzo	MISC	NO	24th Floor-Main Corridors, Private and Freight Elevator Lobbies.	X			Good Condition	
3	12" x 12" Black with White Specks Floor Tile	MISC	NO	24th Floor-Center Corridor Janitor's Closet.		X		Good Condition	
4	Mastic on 12" x 12" Black with White Specks Floor Tile	MISC	NO	24th Floor-Center Corridor Janitor's Closet.		X		Good Condition	
13	Carpet Mastic	MISC	NO	24th Floor-Throughout Courtrooms and Office Areas.			X	N/A	
16	4" Black Vinyl Baseboard	MISC	NO	24th Floor-Janitor's Closet			X	N/A	
17	Adhesive 4" Black Vinyl Baseboard	MISC	NO	24th Floor-Janitor's Closet			X	N/A	
18	1' x 1' Spline Ceiling Tile	MISC	YES	24th Floor-Throughout Floor.			X	N/A	
24	Plaster	SURF	YES	24th Floor-Throughout Floor.			X	N/A	
33	Spray-On (Cementitious)	MISC	NO	24th Floor-On I-Beams Above Drop Ceilings Throughout Floor, Including Electrical Closets.		X		Slight Damage - Debris	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.
40	Canvas Flex Duct	MISC	NO	24th Floor-Inside Perimeter Unit Vents.			X	N/A	
41	Red Sealant on Canvas Flex Duct	MISC	NO	24th Floor-Inside Perimeter Unit Vents.		X		Good Condition	
42	Grey Cementitious Board	MISC	NO	24th Floor-Room 2400 B.		X		Not Observed	Repair or Remove. Label as ACM
43	Electrical Floor Board	MISC	YES	24th Floor-Electrical Closets.		X		Slight Damage	Repair or Remove. Label as ACM
44	Pink Fire Stop	MISC	NO	24th Floor-Electrical Closets.			X	N/A	
47	Electrical Tape	MISC	NO	24th Floor-Telephone Closet North.			X	N/A	
51	Pyro Bar	MISC	YES	24th Floor-Electrical Closets B & C and Rooms 2000 B and Telephone Closet North.			X	N/A	

Summary of Asbestos Bulk Sampling - 24th Floor


Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
52	Mortar on Pyro Bar	MISC	NO	24th Floor-Electrical Closets B & C and Rooms 2000 B and Telephone Closet North			X	N/A	
53	Window Glaze	MISC	NO	24th Floor-Around the inside Perimeter of the Large Windows.			X	N/A	
54	Window Frame Caulk	MISC	NO	24th Floor-Around the Outside Perimeter of the Large Windows.		X		Good Condition	
55	Small Window Glaze	MISC	NO	24th Floor-Stairwell # 3.		X		Good Condition	
57	Red Caulk	SURF	YES	24th Floor-Electrical and Telephone Closets			X	N/A	
58	Black Sealant	MISC	NO	24th Floor-Electrical and Telephone Closets			X	N/A	
76	Fittings on Fiberglass Pipe Insulation	MISC	NO	24th Floor-Pipe Chases and Above Drop Ceilings Throughout Floor.	X			Good Condition	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.
140	Grey Leveling Compound	MISC	NO	24th Floor-Corridor Southeast under Carpet.			X	N/A	

Bold Indicates Asbestos and Assumed Asbestos Containing Materials.

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	1 Terrazzo	X		Good Condition
	3 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	4 Mastic on 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	33 Spray-On (Cementitious)		X	Slight Damage-Debris
	41 Red Sealant on Canvas Duct		X	Good Condition

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	42 Grey Cementitious Board		X	Not Observed
	43 Electrical Floor Board		X	Slight Damage
	54 Window Frame Caulk		X	Good Condition
	55 Small Window Glaze		X	Good Condition
	76 Fitting on Fiberglass Pipe Insulation	X		Good Condition

*Asbestos containing spray applied fire proofing and thermal insulation are present above existing ceiling (Exact locations not shown on drawing)



*Locations of materials updated for this 2015 Reinspection

*Entry into interstitial space above existing ceiling requires 16 hour asbestos training, personal protective equipment and compliance with Building's asbestos operation and maintenance plan

LEGEND:
Material Symbol LOCATIONS OF ASBESTOS CONTAINING MATERIAL

PROJECT NAME:

RICHARD J. DALEY CENTER
50 W. WASHINGTON STREET
CHICAGO, ILLINOIS 60602

PREPARED FOR:

50 W. WASHINGTON STREET
SUITE 1203
CHICAGO, ILLINOIS 60602

SHEET NAME:
2015 ASBESTOS REINSPECTION - 24TH FLOOR
INSPECTED BY: James Lehnhardt
IDPH LICENSE #: 100-04208
DRAWN BY: Emine Bushra Boztepe

PREPARED BY:
Carnow, Conibear & Assoc., Ltd.
Environmental Consulting Services
300 W. Adams St., Suite 1200, Chicago, IL 60606
t: 312.782.4486 f: 312.782.5145
www.ccailld.com



CCA PROJECT NUMBER
A13367-0096
REINSPECTION DATE
DECEMBER, 2015
24TH FLOOR






Summary of Asbestos Bulk Sampling - 25th Floor






Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
1	Terrazzo	MISC	NO	25th Floor-Main Corridors, Private and Freight Elevator Lobbies.	X			Good Condition	
3	12" x 12" Black with White Specks Floor Tile	MISC	NO	25th Floor-Center Corridor Janitor's Closet 2505.		X		Good Condition	
4	Mastic on 12" x 12" Black with White Specks Floor Tile	MISC	NO	25th Floor-Center Corridor Janitor's Closet 2505.		X		Good Condition	
13	Carpet Mastic	MISC	NO	25th Floor-Throughout Courtrooms and Office Areas.			X	N/A	
16	4" Black Vinyl Baseboard	MISC	NO	25th Floor-Janitor's Closet			X	N/A	
17	Adhesive 4" Black Vinyl Baseboard	MISC	NO	25th Floor-Janitor's Closet			X	N/A	
18	1' x 1' Spline Ceiling Tile	MISC	YES	25th Floor-Throughout Floor.			X	N/A	
24	Plaster	SURF	YES	25th Floor-Throughout Floor.			X	N/A	
33	Spray-On (Cementitious)	MISC	NO	25th Floor-On I-Beams Above Drop Ceilings Throughout Floor, Including Electrical Closets.		X		Slight Damage - Debris	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.
40	Canvas Flex Duct	MISC	NO	25th Floor-Inside Perimeter Unit Vents.			X	N/A	
41	Red Sealant on Canvas Flex Duct	MISC	NO	25th Floor-Inside Perimeter Unit Vents.		X		Good Condition	
42	Grey Cementitious Board	MISC	NO	25th Floor-Room 2500 B.		X		Not Observed	Repair or Remove. Label as ACM
43	Electrical Floor Board	MISC	YES	25th Floor-Electrical Closets.		X		Good Condition	Repair or Remove. Label as ACM
44	Pink Fire Stop	MISC	NO	25th Floor-Electrical Closets.			X	N/A	
47	Electrical Tape	MISC	NO	25th Floor-Telephone Closet North.			X	N/A	
49	Elevator Gasket Material	MISC	NO	25th Floor-E.M.R. Room.			X	N/A	
50	Black Filter Material	MISC	NO	25th Floor-E.M.R. Room.			X	N/A	

Summary of Asbestos Bulk Sampling - 25th Floor


Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
51	Pyro Bar	MISC	YES	25th Floor-Electrical Closets B & C and Rooms 2000 B and Telephone Closet North.			X	N/A	
52	Mortar on Pyro Bar	MISC	NO	25th Floor-Electrical Closets B & C and Rooms 2000 B and Telephone Closet North.			X	N/A	
53	Window Glaze	MISC	NO	25th Floor-Around the inside Perimeter of the Large Windows.			X	N/A	
54	Window Frame Caulk	MISC	NO	25th Floor-Around the Outside Perimeter of the Large Windows.		X		Good Condition	
55	Small Window Glaze	MISC	NO	25th Floor-Stairwell # 3.		X		Good Condition	
57	Red Caulk	SURF	YES	25th Floor-Electrical and Telephone Closets.			X	N/A	
58	Black Sealant	MISC	NO	25th Floor-Electrical and Telephone Closets.			X	N/A	
76	Fittings on Fiberglass Pipe Insulation	MISC	NO	25th Floor-Pipe Chases and Above Drop Ceilings Throughout Floor.	X			Good Condition	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.

Bold Indicates Asbestos and Assumed Asbestos Containing Materials.

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	1 Terrazzo	X		Good Condition
	3 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	4 Mastic on 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	33 Spray-On (Cementitious)		X	Slight Damage-Debris
	41 Red Sealant on Canvas Duct		X	Good Condition

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	42 Grey Cementitious Board		X	Not Observed
	43 Electrical Floor Board		X	Slight Damage
	54 Window Frame Caulk		X	Good Condition
	55 Small Window Glaze		X	Good Condition
	76 Fitting on Fiberglass Pipe Insulation	X		Good Condition

*Asbestos containing spray applied fire proofing and thermal insulation are present above existing ceiling (Exact locations not shown on drawing)



*Locations of materials updated for this 2015 Reinspection

*Entry into interstitial space above existing ceiling requires 16 hour asbestos training, personal protective equipment and compliance with Building's asbestos operation and maintenance plan

LEGEND:  LOCATIONS OF ASBESTOS CONTAINING MATERIAL	PROJECT NAME:  RICHARD J. DALEY CENTER 50 W. WASHINGTON STREET CHICAGO, ILLINOIS 60602	PREPARED FOR:  50 W. WASHINGTON STREET SUITE 1203 CHICAGO, ILLINOIS 60602	SHEET NAME: 2015 ASBESTOS REINSPECTION - 25TH FLOOR	PREPARED BY: Carnow, Conibear & Assoc., Ltd. <i>Environmental Consulting Services</i> 300 W. Adams St., Suite 1200, Chicago, IL 60606 t: 312.782.4486 f: 312.782.5145 www.ccailld.com	CCA PROJECT NUMBER A13367-0096
			INSPECTED BY: James Lehnhardt IDPH LICENSE #: 100-04208 DRAWN BY: Emine Bushra Boztepe		REINSPECTION DATE DECEMBER, 2015








25TH FLOOR






Summary of Asbestos Bulk Sampling - 26th Floor

Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
1	Terrazzo	MISC	NO	26th Floor-Main Corridors, Private and Freight Elevator Lobbies.	X			Good Condition	
3	12" x 12" Black with White Specks Floor Tile	MISC	NO	26th Floor-Center Corridor Janitor's Closet.		X		Crack + Missing Tiles	
4	Mastic on 12" x 12" Black with White Specks Floor Tile	MISC	NO	26th Floor-Center Corridor Janitor's Closet.		X		Exposed Damage	
13	Carpet Mastic	MISC	NO	26th Floor-Throughout Courtrooms and Office Areas.			X	N/A	
17	Adhesive 4" Black Vinyl Baseboard	MISC	NO	26th Floor-Janitor's Closet			X	N/A	
18	1' x 1' Spline Ceiling Tile	MISC	YES	26th Floor-Throughout Floor.			X	N/A	
24	Plaster	SURF	YES	26th Floor-Throughout Floor.			X	N/A	
33	Spray-On (Cementitious)	MISC	NO	26th Floor-On I-Beams Above Drop Ceilings Throughout Floor, Including Electrical Closets.		X		Slight Damage - Debris	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.
40	Canvas Flex Duct	MISC	NO	26th Floor-Inside Perimeter Unit Vents.			X	N/A	
41	Red Sealant on Canvas Flex Duct	MISC	NO	26th Floor-Inside Perimeter Unit Vents.		X		Good Condition	
42	Grey Cementitious Board	MISC	NO	26th Floor-Room 2500 B.		X		Not Observed	Repair or Remove. Label as ACM
43	Electrical Floor Board	MISC	YES	26th Floor-Electrical Closets.		X		Slight Damage	Repair or Remove. Label as ACM
44	Pink Fire Stop	MISC	NO	26th Floor-Electrical Closets.			X	N/A	
53	Window Glaze	MISC	NO	26th Floor-Around the inside Perimeter of the Large Windows.			X	N/A	
54	Window Frame Caulk	MISC	NO	26th Floor-Around the Outside Perimeter of the Large Windows.		X		Good Condition	
55	Small Window Glaze	MISC	NO	26th Floor-Stairwell # 3.		X		Good Condition	


Summary of Asbestos Bulk Sampling - 26th Floor

Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
57	Red Caulk	SURF	YES	26th Floor-Electrical and Telephone Closets.			X	N/A	
76	Fittings on Fiberglass Pipe Insulation	MISC	NO	26th Floor-Pipe Chases and Above Drop Ceilings Throughout Floor.		X		Good Condition	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.
140	Grey Leveling Compound	MISC	NO	26th Floor-Under Carpet in Various Areas.			X	N/A	

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	1 Terrazzo	X		Good Condition
	3 12" x 12" Black with White Specks Floor Tile		X	Crack+Missing Tiles
	4 Mastic on 12" x 12" Black with White Specks Floor Tile		X	Exposed Damage
	33 Spray-On (Cementitious)		X	Slight Damage-Debris
	41 Red Sealant on Canvas Duct		X	Good Condition

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	42 Grey Cementitious Board		X	Not Observed
	43 Electrical Floor Board		X	Slight Damage
	54 Window Frame Caulk		X	Good Condition
	55 Small Window Glaze		X	Good Condition
	76 Fitting on Fiberglass Pipe Insulation		X	Good Condition

*Asbestos containing spray applied fire proofing and thermal insulation are present above existing ceiling (Exact locations not shown on drawing)



*Locations of materials updated for this 2015 Reinspection

*Entry into interstitial space above existing ceiling requires 16 hour asbestos training, personal protective equipment and compliance with Building's asbestos operation and maintenance plan

LEGEND:  LOCATIONS OF ASBESTOS CONTAINING MATERIAL	PROJECT NAME:  RICHARD J. DALEY CENTER 50 W. WASHINGTON STREET CHICAGO, ILLINOIS 60602	PREPARED FOR:  50 W. WASHINGTON STREET SUITE 1203 CHICAGO, ILLINOIS 60602	SHEET NAME: 2015 ASBESTOS REINSPECTION - 26TH FLOOR	PREPARED BY: Carnow, Conibear & Assoc., Ltd. Environmental Consulting Services 300 W. Adams St., Suite 1200, Chicago, IL 60606 t: 312.782.4486 f: 312.782.5145 www.ccailld.com	CCA PROJECT NUMBER A13367-0096 REINSPECTION DATE DECEMBER, 2015 26TH FLOOR
			INSPECTED BY: James Lehnhardt IDPH LICENSE #: 100-04208 DRAWN BY: Emine Bushra Boztepe		








Summary of Asbestos Bulk Sampling - 27th Floor






Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
1	Terrazzo	MISC	NO	27th Floor-Main Corridors, Private and Freight Elevator Lobbies.	X			Good Condition	
3	12" x 12" Black with White Specks Floor Tile	MISC	NO	27th Floor-Room 2729.		X		Damage, cracked, missing	
4	Mastic on 12" x 12" Black with White Specks Floor Tile	MISC	NO	27th Floor-Room 2729.		X		Good Condition	
10	Computer Flooring	MISC	NO	27th Floor-Computer Room.			X	N/A	
13	Carpet Mastic	MISC	NO	27th Floor-Throughout Courtrooms and Office Areas.			X	N/A	
17	Adhesive 4" Black Vinyl Baseboard	MISC	NO	27th Floor-Janitor's Closet			X	N/A	
18	1' x 1' Spline Ceiling Tile	MISC	YES	27th Floor-Throughout Floor.			X	N/A	
19	1' x 1' Ceiling Tile	MISC	YES	27th Floor-Room 2730.			X	N/A	
20	Adhesive on 1' x 1' Ceiling Tile	MISC	NO	27th Floor-Room 2730.			X	N/A	
24	Plaster	SURF	YES	27th Floor-Throughout Floor.			X	N/A	
33	Spray-On (Cementitious)	MISC	NO	27th Floor-On I-Beams Above Drop Ceilings Throughout Floor, Including Electrical Closets.		X		Slight Damage - Debris	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.
40	Canvas Flex Duct	MISC	NO	27th Floor-Inside Perimeter Unit Vents.			X	N/A	
41	Red Sealant on Canvas Flex Duct	MISC	NO	27th Floor-Inside Perimeter Unit Vents.		X		Good Condition	
42	Grey Cementitious Board	MISC	NO	27th Floor-Room 2500 B.		X		Not Observed	Repair or Remove. Label as ACM
43	Electrical Floor Board	MISC	YES	27th Floor-Electrical Closets.		X		Slight Damage	Repair or Remove. Label as ACM
44	Pink Fire Stop	MISC	NO	27th Floor-Electrical Closets.			X	N/A	

Summary of Asbestos Bulk Sampling - 27th Floor


Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
53	Window Glaze	MISC	NO	27th Floor-Around the inside Perimeter of the Large Windows.			X	N/A	
54	Window Frame Caulk	MISC	NO	27th Floor-Around the Outside Perimeter of the Large Windows.	X			Good Condition	
55	Small Window Glaze	MISC	NO	27th Floor-Stairwell # 3.		X		Good Condition	
57	Red Caulk	SURF	YES	27th Floor-Electrical and Telephone Closets.			X	N/A	
76	Fittngs on Fiberglass Pipe Insulation	MISC	NO	27th Floor-Pipe Chases and Above Drop Ceilings Throughout Floor.		X		Good Condition	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.

Bold Indicates Asbestos and Assumed Asbestos Containing Materials.

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	1 Terrazzo	X		Good Condition
	3 12" x 12" Black with White Specks Floor Tile		X	Damaged, cracked, missing
	4 Mastic on 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	33 Spray-On (Cementitious)		X	Slight Damage-Debris
	41 Red Sealant on Canvas Duct		X	Good Condition

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	42 Grey Cementitious Board		X	Not Observed
	43 Electrical Floor Board		X	Slight Damage
	54 Window Frame Caulk	X		Good Condition
	55 Small Window Glaze		X	Good Condition
	76 Fitting on Fiberglass Pipe Insulation		X	Good Condition

*Asbestos containing spray applied fire proofing and thermal insulation are present above existing ceiling (Exact locations not shown on drawing)



*Locations of materials updated for this 2015 Reinspection

*Entry into interstitial space above existing ceiling requires 16 hour asbestos training, personal protective equipment and compliance with Building's asbestos operation and maintenance plan

LEGEND:
Material Symbol LOCATIONS OF ASBESTOS CONTAINING MATERIAL

PROJECT NAME:

RICHARD J. DALEY CENTER
50 W. WASHINGTON STREET
CHICAGO, ILLINOIS 60602

PREPARED FOR:

50 W. WASHINGTON STREET
SUITE 1203
CHICAGO, ILLINOIS 60602

SHEET NAME:
2015 ASBESTOS REINSPECTION - 27TH FLOOR
INSPECTED BY: James Lehnhardt
IDPH LICENSE #: 100-04208
DRAWN BY: Emine Bushra Boztepe

PREPARED BY:
Carnow, Conibear & Assoc., Ltd.
Environmental Consulting Services
300 W. Adams St., Suite 1200, Chicago, IL 60606
t: 312.782.4486 f: 312.782.5145
www.ccailld.com



CCA PROJECT NUMBER
A13367-0096
REINSPECTION DATE
DECEMBER, 2015
27TH FLOOR






Summary of Asbestos Bulk Sampling - 28th Floor





Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
1	Terrazzo	MISC	NO	28th Floor-Main Corridors, Private and Freight Elevator Lobbies.	X			Good Condition	
13	Carpet Mastic	MISC	NO	28th Floor-Throughout Courtrooms and Office Areas.		X		Good Condition	
15	Black Mastic	MISC	NO	28th Floor-2800 Janitor's Closet.		X		Good Condition	
18	1' x 1' Spline Ceiling Tile	MISC	YES	28th Floor-Throughout Floor.			X	N/A	
24	Plaster	SURF	YES	28th Floor-Throughout Floor.			X	N/A	
33	Spray-On (Cementitious)	MISC	YES	28th Floor-On I-Beams in Electrical Closets.		X		Slight Damage	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.
34	Spray-On (Fluffy)	MISC	YES	28th Floor-Hallways and Perimeter of Building.			X	N/A	
35	Spray-On (Lt. Beige)	MISC	YES	28th Floor-Hallways and Perimeter of Building.			X	N/A	
40	Canvas Flex Duct	MISC	NO	28th Floor-Inside Perimeter Unit Vents.			X	N/A	
41	Red Sealant on Canvas Flex Duct	MISC	NO	28th Floor-Inside Perimeter Unit Vents.	X			Good Condition	
43	Electrical Floor Board	MISC	YES	28th Floor-Electrical Closets.		X		Physical Damage	Repair or Remove. Label as ACM
44	Pink Fire Stop	MISC	NO	28th Floor-Electrical Closets.			X	N/A	
53	Window Glaze	MISC	NO	28th Floor-Around the inside Perimeter of the Large Windows.			X	N/A	
54	Window Frame Caulk	MISC	NO	28th Floor-Around the Outside Perimeter of the Large Windows.	X			Good Condition	
55	Small Window Glaze	MISC	NO	28th Floor-Stairwell # 3.	X			Good Condition	
57	Red Caulk	SURF	YES	28th Floor-Electrical and Telephone Closets.			X	N/A	
58	Black Sealant	MISC	NO	28th Floor-Electrical Closets.			X	N/A	

Summary of Asbestos Bulk Sampling - 28th Floor


Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
64	Brown Duct Sealant	MISC	NO	8th Floor-Above Drop Ceiling.			X	N/A	
76	Fittngs on Fiberglass Pipe Insulation	MISC	NO	28th Floor-Pipe Chases and Above Drop Ceilings Throughout Floor.	X			Good Condition	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.
140	Leveling Compound	MISC	YES	28th Floor-Electrical Closet.			X	N/A	

Bold Indicates Asbestos and Assumed Asbestos Containing Materials.

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	1 Terrazzo	X		Good Condition
	13 Carpet Mastic		X	Good Condition
	15 Black Mastic		X	Good Condition
	33 Spray-On (Cementitious)		X	Slight Damage
	41 Red Sealant on Canvas Duct	X		Good Condition

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	43 Electrical Floor Board		X	Physical Damage
	54 Window Frame Caulk	X		Good Condition
	55 Small Window Glaze	X		Good Condition
	76 Fitting on Fiberglass Pipe Insulation	X		Good Condition

*Asbestos containing spray applied fire proofing and thermal insulation are present above existing ceiling (Exact locations not shown on drawing)



*Locations of materials updated for this 2015 Reinspection

*Entry into interstitial space above existing ceiling requires 16 hour asbestos training, personal protective equipment and compliance with Building's asbestos operation and maintenance plan

LEGEND:
Material Symbol LOCATIONS OF ASBESTOS CONTAINING MATERIAL

PROJECT NAME:

RICHARD J. DALEY CENTER
50 W. WASHINGTON STREET
CHICAGO, ILLINOIS 60602

PREPARED FOR:

50 W. WASHINGTON STREET
SUITE 1203
CHICAGO, ILLINOIS 60602

SHEET NAME:
2015 ASBESTOS REINSPECTION - 28TH FLOOR
INSPECTED BY:
IDPH LICENSE #:
DRAWN BY: Emine Bushra Boztepe

PREPARED BY:
Carnow, Conibear & Assoc., Ltd.
Environmental Consulting Services
300 W. Adams St., Suite 1200, Chicago, IL 60606
t: 312.782.4486 f: 312.782.5145
www.ccailld.com



CCA PROJECT NUMBER
A13367-0096
REINSPECTION DATE
DECEMBER, 2015
28TH FLOOR






Summary of Asbestos Bulk Sampling - 29th Floor





Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
1	Terrazzo	MISC	NO	29th Floor-Main Corridors, Private and Freight Elevator Lobbies.	X			Good Condition	
3	12" x 12" Black with White Specks Floor Tile	MISC	NO	29th Floor-2900 East and West and under Carpet in Offices.		X		Partially Removed	Partial Abatement June 2015
4	Mastic on 12" x 12" Black with White Specks Floor Tile	MISC	NO	29th Floor-2900 East and West and under Carpet in Offices.		X		Good Condition	
13	Carpet Mastic	MISC	NO	29th Floor-Office Areas.			X	N/A	
18	1' x 1' Spline Ceiling Tile	MISC	YES	29th Floor-Throughout Floor.			X	N/A	
24	Plaster	SURF	YES	29th Floor-Throughout Floor.			X	N/A	
33	Spray-On (Cementitious)	MISC	NO	29th Floor-On I-Beams Above Drop Ceilings Throughout Floor, Including Electrical Closets.		X		Slight Damage - Debris	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.
40	Canvas Flex Duct	MISC	NO	29th Floor-Inside Perimeter Unit Vents.			X	N/A	
41	Red Sealant on Canvas Flex Duct	MISC	NO	29th Floor-Inside Perimeter Unit Vents.	X			Good Condition	
43	Electrical Floor Board	MISC	YES	29th Floor-Electrical Closets.		X		Slight Damage	Repair or Remove. Label as ACM
44	Pink Fire Stop	MISC	YES	29th Floor-Electrical Closets.			X	N/A	
45	White Fire Stop	MISC	NO	29th Floor-Electrical Closets.			X	N/A	
51	Pyro Bar	MISC	YES	29th Floor-Electrical Closets.			X	N/A	
52	Mortar on Pyro Bar	MISC	NO	29th Floor-Electrical Closets.			X	N/A	
53	Window Glaze	MISC	NO	29th Floor-Around the inside Perimeter of the Large Windows.			X	N/A	
54	Window Frame Caulk	MISC	NO	29th Floor-Around the Outside Perimeter of the Large Windows.		X		Good Condition	
55	Small Window Glaze	MISC	NO	29th Floor-Stairwell # 3.	X			Good Condition	
57	Red Caulk	SURF	YES	29th Floor-Electrical and Telephone Closets.			X	N/A	

Summary of Asbestos Bulk Sampling - 29th Floor


Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
58	Black Sealant	MISC	NO	29th Floor-Electrical and Telephone Closets.			X	N/A	
60	Grey Wall Sealant	MISC	NO	29th Floor-Electrical Closets.			X	N/A	
76	Fittngs on Fiberglass Pipe Insulation	MISC	NO	29th Floor-Pipe Chases and Above Drop Ceilings Throughout Floor.	X			Good Condition	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.
77	Misc. Insulation	MISC	YES	29th Floor-Electrical Closets.			X	N/A	

Bold Indicates Asbestos and Assumed Asbestos Containing Materials.

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	1 Terrazzo	X		Good Condition
	3 12" x 12" Black with White Specks Floor Tile		X	Partially Removed
	4 Mastic on 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	33 Spray-On (Cementitious)		X	Slight Damage-Debris
	41 Red Sealant on Canvas Flex Duct	X		Good Condition

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	43 Electrical Floor Board		X	Slight Damage
	54 Window Frame Caulk		X	Good Condition
	55 Small Window Glaze	X		Good Condition
	76 Fitting on Fiberglass Pipe Insulation	X		Good Condition

*Asbestos containing spray applied fire proofing and thermal insulation are present above existing ceiling (Exact locations not shown on drawing)



*Locations of materials updated for this 2015 Reinspection

*Entry into interstitial space above existing ceiling requires 16 hour asbestos training, personal protective equipment and compliance with Building's asbestos operation and maintenance plan

LEGEND:  LOCATIONS OF ASBESTOS CONTAINING MATERIAL	PROJECT NAME:  RICHARD J. DALEY CENTER 50 W. WASHINGTON STREET CHICAGO, ILLINOIS 60602	PREPARED FOR:  50 W. WASHINGTON STREET SUITE 1203 CHICAGO, ILLINOIS 60602	SHEET NAME: 2015 ASBESTOS REINSPECTION - 29TH FLOOR	PREPARED BY: Carnow, Conibear & Assoc., Ltd. Environmental Consulting Services 300 W. Adams St., Suite 1200, Chicago, IL 60606 t: 312.782.4486 f: 312.782.5145 www.ccailld.com	CCA PROJECT NUMBER A13367-0096 REINSPECTION DATE DECEMBER, 2015 29TH FLOOR
			INSPECTED BY: IDPH LICENSE #:		







Summary of Asbestos Bulk Sampling - 30th Floor




Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
1	Terrazzo	MISC	NO	30th Floor-Main Corridors, Private and Freight Elevator Lobbies.	X			Good Condition	
13	Carpet Mastic	MISC	NO	30th Floor-Throughout Courtrooms and Office Areas.			X	N/A	
18	1' x 1' Spline Ceiling Tile	MISC	YES	30th Floor-Throughout Floor.			X	N/A	
24	Plaster	SURF	YES	30th Floor-Throughout Floor.			X	N/A	
33	Spray-On (Cementitious)	MISC	YES	30th Floor-On I-Beams in Electrical Closets.	X			Slight Damage	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.
34	Spray-On (Grey Fluffy)	MISC	YES	30th Floor-Above Drop Ceilings.			X	N/A	
40	Canvas Flex Duct	MISC	NO	30th Floor-Inside Perimeter Unit Vents.			X	N/A	
41	Red Sealant on Canvas Flex Duct	MISC	NO	30th Floor-Inside Perimeter Unit Vents.	X			Good Condition	
43	Electrical Floor Board	MISC	YES	30th Floor-Electrical Closets.		X		Physical Damage	Repair or Remove. Label as ACM
46	Grey Fire Stop	MISC	NO	30th Floor-Electrical Closets.			X	N/A	
53	Window Glaze	MISC	NO	30th Floor-Around the inside Perimeter of the Large Windows.			X	N/A	
54	Window Frame Caulk	MISC	NO	30th Floor-Around the Outside Perimeter of the Large Windows.	X			Good Condition	
55	Small Window Glaze	MISC	NO	30th Floor-Stairwell # 3.	X			Good Condition	
57	Red Caulk	SURF	YES	30th Floor-Electrical and Telephone Closets.			X	N/A	
65	White Sealant on Duct	MISC	NO	30th Floor-Above Drop Ceilings.			X	N/A	
66	Wall Caulk	MISC	NO	30th Floor-			X	N/A	

Summary of Asbestos Bulk Sampling - 30th Floor


Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
76	Fittngs on Fiberglass Pipe Insulation	MISC	NO	30th Floor-Pipe Chases and Above Drop Ceilings Throughout Floor.	X			Good Condition	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.

Bold Indicates Asbestos and Assumed Asbestos Containing Materials.

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	1 Terrazzo	X		Good Condition
	33 Spray-On (Cementitious)	X		Slight Damage
	41 Red Sealant on Canvas Duct	X		Good Condition
	43 Electrical Floor Board		X	Physical Damage

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	54 Window Frame Caulk	X		Good Condition
	55 Small Window Glaze	X		Good Condition
	76 Fitting on Fiberglass Pipe Insulation	X		Good Condition

*Asbestos containing spray applied fire proofing and thermal insulation are present above existing ceiling (Locations not shown on drawing)



*Locations of materials updated for this 2015 Reinspection

LEGEND:
Material Symbol LOCATIONS OF ASBESTOS CONTAINING MATERIAL

PROJECT NAME:

RICHARD J. DALEY CENTER
50 W. WASHINGTON STREET
CHICAGO, ILLINOIS 60602

PREPARED FOR:

50 W. WASHINGTON STREET
SUITE 1203
CHICAGO, ILLINOIS 60602

SHEET NAME:
2015 ASBESTOS REINSPECTION - 30TH FLOOR
INSPECTED BY: Douglas McCormick
IDPH LICENSE #: 100-08904
DRAWN BY: Emine Bushra Boztepe

PREPARED BY:
Carnow, Conibear & Assoc., Ltd.
Environmental Consulting Services
300 W. Adams St., Suite 1200, Chicago, IL 60606
t: 312.782.4486 f: 312.782.5145
www.ccailld.com



CCA PROJECT NUMBER
A13367-0096
REINSPECTION DATE
DECEMBER, 2015
30TH FLOOR

Summary of Asbestos Bulk Sampling - 31st Floor & Mechanical Spaces

Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
3	12" x 12" Black with White Specs Floor Tile	MISC	NO	31st Floor & M-3		X		Good Condition	
4	Mastic on 12" x 12" Black with White Specs Floor Tile	MISC	NO	31st Floor & M-3		X		Good Condition, Physical Damage (M-3)	
19	1' x 1' Ceiling Tile	MISC	YES	31st Floor			X	N/A	
24	Plaster	SURF	NO	31st Floor, M-1, M-2, M-3 & Penthouse			X	N/A	
33	Spray-On (Cemetitious)	SURF	YES	31st Floor, M-1, M-2, M-3 & Cooling Tower		X		Good Condition	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.
37	Spray-On (G-4 Ceiling)	SURF	YES	31st Floor			X	N/A	
38	Spray-On (G-3 Ceiling)	SURF	YES	31st Floor			X	N/A	
39	Spray-On (Electrical Room Ceiling)	SURF	YES	31st Floor			X	N/A	
39	Spray-On (Mechanical Space)	SURF	YES	Mechanical Space M-1		X		Good Condition	
43	Electrical Floor Board	MISC	YES	31st Floor		X		Physical Damage	Repair or Remove. Label as ACM
45	White Fire Stop	MISC	YES	31st Floor			X	N/A	
55	Small Window Glaze	MISC	NO	31st Floor, M-1, M-2 & M-3	X			Good Condition	
69	Interior Air Chamber Black Sealant	MISC	NO	31st Floor-Material is in open space up to M-3.		X		Good Condition	
70	Duct Floor Barrier/Sealant	MISC	YES	31st Floor			X	N/A	
71	Air Chamber Caulk (White)	MISC	NO	31st Floor		X		Good Condition	











Summary of Asbestos Bulk Sampling - 31st Floor & Mechanical Spaces











Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
76	Fittings on Fiberglass Pipe Insulation	TSI	YES	Penthouse	X			Good Condition	Entry into above ceiling interstitial spaces shall follow requirements detailed in Building Asbestos Operations & Maintenance Program.
85	Fittings on Lo-Press. Condensate	TSI	YES	31s Floor-Material is in open space up to M-3.		X		Good Condition	
86	Fittings on Hi-Press. Steam Pipes	TSI	YES	31st Floor-Material is in open space up to M-3.		X		Good Condition	
97	Fittings on Hot Water Pump	TSI	YES	M-2		X		Good Condition	
116	Air Chamber Door Frame Gasket	MISC	YES	31st Floor			X	N/A	
117	Red Sealant inside Fan Housing	MISC	NO	31st and M-1		X		Good Condition	
118	Valve Housing on Hi-Press. Steam Pipes	TSI	YES	31st Floor		X		Slight Damage	
119	Air Chamber Seam Tape	MISC	NO	31st Floor and M-1		X		Good Condition	
120	Duct Insulation	TSI	YES	31st Floor-Material is in open spae up to M-3		X		Good Condition	
121	Blower Unit Seam Tape	MISC	NO	31st Floor			X	N/A	
	Large Round Duct Seam Tape	MISC	NO	31st Floor			X	N/A	
123	Diesel Generator Exhaust Fittings	TSI	YES	31st Floor-Material is in open spae up to M-3		X		Good Condition	
124	Diesel Generator Exhaust Muffler	TSI	YES	31st Floor			X	N/A	
125	Fan Unit Door Insulation	MISC	YES	31st Floor			X	N/A	
126	Fittings on Gas Pipes (Yellow)	TSI	YES	31st Floor-Material is in open spae up to M-3		X		Good Condition	
127	Fittings on Chilled Water Supply	TSI	YES	31st Floor-Material is in open spae up to M-3		X		Good Condition	
128	Fittings on Chilled Water Return	TSI	YES	31st Floor-Material is in open spae up to M-3		X		Good Condition	
129	Condensate Tank	TSI	YES	31st Floor		X		Good Condition	
130	Fittings on Domestic Water Pipe (Blue)	TSI	YES	31st Floor			X	N/A	

Summary of Asbestos Bulk Sampling - 31st Floor & Mechanical Spaces


Homogenous Area	Material Description	Category	Friable	General Material Location	Asbestos Containing Material			2015 Condition Assessment	Comments
					Assumed	Positive	Negative		
131	Fittings on Drain Pipe (Black)	TSI	YES	31st Floor-Material is in open spae up to M-3		X		Good Condition	
132	Vibration Floor Groove Insulation	MISC	YES	31st Floor			X	N/A	
133	Fittings on Cooling Tower Pipe	TSI	YES	M-1		X		Good Condition	
134	Fittings on Water Pipes	TSI	YES	31st Floor, M-1 & M-2		X		Good Condition	
135	Grey Holding Tank	TSI	YES	M-2		X		Good Condition	
136	Vibration Damper (Ventglass)	MISC	NO	31st Floor			X	N/A	

Bold Indicates Asbestos and Assumed Asbestos Containing Materials.


Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	3 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	4 Mastic on 12" x 12" Black with White Specks Floor Tile		X	Good Condition
	33 Spray-On (Cementitious)		X	Good Condition
	43 Electrical Floor Board		X	Physical Damage
	55 Small Window Glaze	X		Good Condition
	69 Interior Air Chamber Black Sealant		X	Good Condition
	71 Air Chamber Caulk (White)		X	Good Condition
	85 Fittings on Lo-Press		X	Good Condition
	86 Fittings on Hi-Press. Steam Pipes		X	Good Condition
	117 Red Sealant inside Fan Housing		X	Good Condition

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	118 Valve Housing on Hi-Press. Steam Pipes		X	Slight Damage
	119 Air Chamber Seam Tape		X	Good Condition
	120 Duct Insulation		X	Good Condition
	123 Diesel Generator Exhaust Fittings		X	Good Condition
	126 Fittings on Gas Pipes (Yellow)		X	Good Condition
	127 Fittings on Chilled Water Supply		X	Good Condition
	128 Fittings on Chilled Water Return		X	Good Condition
	129 Condensate Tank		X	Good Condition
	131 Fittings on Drain Pipe (Black)		X	Good Condition
	134 Fittings on Water Pipes		X	Good Condition

*Asbestos containing spray applied fire proofing and thermal insulation are present throughout floor.



*Locations of materials updated for this 2015 Reinspection

LEGEND:
 LOCATIONS OF ASBESTOS CONTAINING MATERIAL

PROJECT NAME:

RICHARD J. DALEY CENTER
 50 W. WASHINGTON STREET
 CHICAGO, ILLINOIS 60602

PREPARED FOR:

MB Real Estate
 50 W. WASHINGTON STREET
 SUITE 1203
 CHICAGO, ILLINOIS 60602

SHEET NAME:
 2015 ASBESTOS REINSPECTION - 31ST FLOOR

INSPECTED BY: Douglas McCormick

IDPH LICENSE #: 100-08904

DRAWN BY: Emine Bushra Boztepe





PREPARED BY:
 Carnow, Conibear & Assoc., Ltd.
 Environmental Consulting Services
 300 W. Adams St., Suite 1200, Chicago, IL 60606
 t: 312.782.4486 f: 312.782.5145
 www.ccailld.com






CCA PROJECT NUMBER
 A13367-0096


REINSPECTION DATE
 DECEMBER, 2015

31ST FLOOR


Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
 39	Spray-On (Mechanical Space)		X	Good Condition
 55	Small Window Glaze	X		Good Condition
 117	Red Sealant inside Fan Housing		X	Good Condition
 119	Air Chamber Seam Tape		X	Good Condition

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
 131	Fittings on Drain Pipe (Black)		X	Good Condition
 133	Fittings on Cooling Tower Pipe (Black)		X	Good Condition
 134	Fittings on Water Pipes		X	Good Condition

*Asbestos containing spray applied fire proofing and thermal insulation are present.



*Locations of materials updated for this 2015 Reinspection

LEGEND:
 LOCATIONS OF ASBESTOS CONTAINING MATERIAL

PROJECT NAME:

RICHARD J. DALEY CENTER
 50 W. WASHINGTON STREET
 CHICAGO, ILLINOIS 60602

PREPARED FOR:

MB Real Estate
 50 W. WASHINGTON STREET
 SUITE 1203
 CHICAGO, ILLINOIS 60602




SHEET NAME:
 2015 ASBESTOS REINSPECTION - M-1 31ST FLOOR
 INSPECTED BY: Douglas McCormick
 IDPH LICENSE #: 100-08904
 DRAWN BY: Emine Bushra Boztepe




PREPARED BY:

 Carnow, Conibear & Assoc., Ltd.
 Environmental Consulting Services
 300 W. Adams St., Suite 1200, Chicago, IL 60606
 t: 312.782.4486 f: 312.782.5145
 www.ccaltd.com


**CARNOW
 CONIBEAR**

CCA PROJECT NUMBER
 A13367-0096
 REINSPECTION DATE
 DECEMBER, 2015
**31ST FLOOR
 M-1**

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
 33	Spray-On (Cementitious)		X	Good Condition
 55	Small Window Glaze	X		Good Condition
 97	Fittings on Hot Water Pump		X	Good Condition




Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
 134	Fittings on Water Pipes		X	Good Condition
 135	Grey Holding Tank		X	Good Condition
 134	Fittings on Steam Lines		X	Good Condition




*Asbestos containing spray applied fire proofing and thermal insulation are present above existing ceiling (Locations not shown on drawing)




*Locations of materials updated for this 2015 Reinspection

LEGEND:  LOCATIONS OF ASBESTOS CONTAINING MATERIAL	PROJECT NAME:  RICHARD J. DALEY CENTER 50 W. WASHINGTON STREET CHICAGO, ILLINOIS 60602	PREPARED FOR:  50 W. WASHINGTON STREET SUITE 1203 CHICAGO, ILLINOIS 60602	SHEET NAME: 2015 ASBESTOS REINSPECTION - M-2 31ST FLOOR	PREPARED BY: Carnow, Conibear & Assoc., Ltd. Environmental Consulting Services 300 W. Adams St., Suite 1200, Chicago, IL 60606 t: 312.782.4486 f: 312.782.5145 www.ccalltd.com	CCA PROJECT NUMBER A13367-0096
			INSPECTED BY: Douglas McCormick IDPH LICENSE #: 100-08904 DRAWN BY: Emine Bushra Boztepe		REINSPECTION DATE DECEMBER, 2015 

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	3 12" x 12" Black with White Specks Floor Tile		X	Not Present
	4 Mastic on 12" x 12" Black with White Specks Floor Tile		X	Not Present
	33 Spray-On (Cementitious)		X	Physical Damage

Material Symbol	Material Description	Asbestos Results		2015 Condition Assessment
		Assumed	Positive	
	55 Small Window Glaze	X		Good Condition
	76 Fitting on Fiberglass Pipe Insulation	X		Good Condition
	Green Spray-on	X		Good Condition

*Asbestos containing spray applied fire proofing and thermal insulation are present above existing ceiling (Locations not shown on drawing)



*Locations of materials updated for this 2015 Reinspection

*Entry into interstitial space above existing ceiling requires 16 hour asbestos training, personal protective equipment and compliance with Building's asbestos operation and maintenance plan

LEGEND:  LOCATIONS OF ASBESTOS CONTAINING MATERIAL	PROJECT NAME:  RICHARD J. DALEY CENTER 50 W. WASHINGTON STREET CHICAGO, ILLINOIS 60602	PREPARED FOR:  50 W. WASHINGTON STREET SUITE 1203 CHICAGO, ILLINOIS 60602	SHEET NAME: 2015 ASBESTOS REINSPECTION - M-3 31ST FLOOR	PREPARED BY: Carnow, Conibear & Assoc., Ltd. Environmental Consulting Services 300 W. Adams St., Suite 1200, Chicago, IL 60606 t: 312.782.4486 f: 312.782.5145 www.ccalltd.com	CCA PROJECT NUMBER A13367-0096
			INSPECTED BY: Douglas McCormick IDPH LICENSE #: 100-08904 DRAWN BY: Emine Bushra Boztepe		REINSPECTION DATE DECEMBER, 2015 